

LAPORAN REPAIR KOMATSU INDONESIA

Tanggal Repair	03-Oct-23
Jam Berangkat	07.55 S/D 09.15 WIB
Jam Repair	09.15 S/D 10.30
Jam Kembali	-
Qty Unit Repair	2 Pcs
Assy No	21T-06-44661-01 dan 14X06J1150-00
Type Unit	-
Jumlah Man Power	2 orang
Driver	1 orang
Methode Repair	Repair salah setting dan Buzzer ulang

Maker of Harness ☒ BEI ☐ NON BEI


Couse of Defect ☒ BEI ☐ NON BEI

MATERIAL UNTUK REPAIR :


PART NAME	PART NO	QTY
-	-	-

1. Buzzer ulang, pasang name plate dan tape OK assy 21T-06-44661-01

Before :



After :




2. Repair assy 14X06J1150-00 pada posisi CN5 dan CN8 NG salah setting


CN5 : Std : B , Y
Act : W , B - Y

CN8 : Std : W , B - Y
Act : B , Y

Before :



After :



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
Asst Manager QA	Leader QA	Repairman