

LAPORAN REPAIR KOMATSU INDONESIA

Tanggal Repair	16-Feb-24
Jam Berangkat	09.10 WIB
Jam Repair	11.05 S/D 15.30
Jam Kembali	17.55 WIB
Qty Unit Repair	21 pcs
Assy No	22150615-00
Type Unit	PC135F-10M0
Jumlah Man Power	1 Orang
Driver	-
Methode Repair	Potong Wire ganti terminal dan pasang connector

Maker of Harness ☐ BEI ☐ NON BEI

Cause of Defect ☐ BEI ☐ NON BEI




MATERIAL UNTUK REPAIR :

PART NAME	PART NO	QTY
Terminal	7116-2874	21 Pcs
Rubber seal	7157-2571-80	21 Pcs
Connector	7123-6214-40	21 Pcs


1.Modif harness PC135F pada posisi AC03 dari connector DT ke connector 7123-6214-40 sebanyak 21 pcs

Before :


After :



2.Assy No



3.Type Unit



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
Asst Manager QA	Leader QA	Repairman