

LAPORAN REPAIR KOMATSU INDONESIA

Tanggal Repair	18-Mar-24
Jam Berangkat	07.50 WIB
Jam Repair	09.30 S/D 14.30 WIB
Jam Kembali	18.00 WIB
Qty Unit Repair	23 pcs
Assy No	22150615-00
Type Unit	PC135F-10M0 dan HM400
Jumlah Man Power	1 Orang
Driver	1 Orang
Methode Repair	Polong Wire ganti terminal dan pasang connector

Maker of Harness ☐ BEI ☒ NON BEI




Couse of Defect ☐ BEI ☒ NON BEI

MATERIAL UNTUK REPAIR :

PART NAME	PART NO	QTY
Terminal	7116-2874	21 Pcs
Rubber seal	7157-2571-80	21 Pcs
Connector	7123-6214-40	21 Pcs
Terminal	B1.25	4 Pcs
SH Tube	ES2000-1	100 mm
SH Tube	ES2000-3	80 mm

1.Modif harness PC135F pada posisi AC03 dari connector DT ke connector 7123-6214-40 sebanyak 21 pcs



Before :





After :

2.Repair kabel untuk jaringan radio dan GPS unit HM400 masing-masing 1 pcs

Before :




After :



4.Assy No

5.Type Unit



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
Asst Manager QA	Leader QA	Repairman