

LAPORAN REPAIR KOMATSU INDONESIA

Tanggal Repair	22-Mar-24
Jam Berangkat	07.45 WIB
Jam Repair	11.20 s/d 15.55
Jam Kembali	19.50 WIB
Qty Unit Repair	3 pcs
Type Unit	PC 135 HARVESTER dan D85
Jumlah Man Power	2 Orang
Driver	-
Methode Repair	Potong wire ganti terminal dan pasang conector


Maker of Harness ☐ BEI ☒ NON BEI

Cause of Defect ☐ BEI ☒ NON BEI


MATERIAL UNTUK REPAIR :

PART NAME	PART NO	QTY
Terminal	1062-16-0122	24 Pcs
Terminal	1060-16-0122	17 Pcs
Terminal	+MT080-0123	4 Pcs
Terminal	+R1.25-5	2 Pcs
Terminal	+R1.25-8	2 Pcs
Wire	AVSS 0.5 B	2400 mm
Wire	AVSS 0.5 W	1200 mm
Connector	DT06-6S-EP06	2 Pcs
Connector	DT04-6P-E005	2 Pcs
Connector	DT04-2P-E005	3 Pcs
Retainer	W2P	3 Pcs
Retainer	W6P	2 Pcs
Retainer	W6S-P012	2 Pcs
Connector	+7124-9681	2 Pcs
Tape	WHVTA 19*20 B	200 mm
Fuse 10 A	+7123+3011	2 Pcs
Connector	DT06-8SA-CE05	2 Pcs
Retainer	W8S-P012	2 Pcs


1. Modif PC 135 HARVESTER sebanyak 2 unit




2. Sambung wire



3. Modif connector pada Oil Cooler sebanyak 2 pcs



4. Repair pasang terminal dan connector untuk unit D85 sebanyak 1 unit



5. Type Unit



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
Ass Manager QA	Leader QA	Repairman