

LAPORAN REPAIR KOMATSU INDONESIA

Tanggal Repair	27-Apr-24
Jam Berangkat	07.00 WIB
Jam Repair	09.10 s/d 14.45
Jam Kembali	17.50 WIB
Qty Unit Repair	5 pcs
Type Unit	PC 135 HARVESTER,D155 dan HM 400
Jumlah Man Power	1 Orang
Driver	1 Orang
Methode Repair	Potong wire ganti terminal dan pasang conector



Maker of Harness ☐ BEI ☒ NON BEI
 Cause of Defect ☐ BEI ☒ NON BEI

MATERIAL UNTUK REPAIR :


PART NAME	PART NO	QTY
Terminal	1062-16-0122	36 Pcs
Terminal	1060-16-0122	14 Pcs
Terminal	+MT080-0123	6 Pcs
Terminal	+R1.25-5	3 Pcs
Terminal	+R1.25-8	3 Pcs
Wire	AVSS 0.5 B	2400 mm
Wire	AVSS 0.5 W	1200 mm
Connector	DT06-6S-EP06	3 Pcs
Connector	DT04-6P-E005	3 Pcs
Connector	DT04-2P-E005	2 Pcs
Retainer	W2P	2 Pcs
Retainer	W6P	3 Pcs
Retainer	W6S-P012	3 Pcs
Connector	+7124-9681	3 Pcs
Tape	WHVTA 19*20 B	200 mm
Fuse 10 A	+7123+3011	3 Pcs
Connector	DT06-8SA-CE05	3 Pcs
Terminal	+R1.25-8	1 Pcs
Connector	DT06-8SA-CE05	3 Pcs
Retainer	W8S-P012	3 Pcs

1. Modif PC 135 HARVESTER sebanyak 3 unit

BEFORE



AFTER




2. Sambung wire

Before



After



3. Modif connector pada Oil Cooler sebanyak 2 pcs

Before



After



4. Repair pasang terminal untuk unit D 155 sebanyak 1 unit

Before



After



5. Repair pasang terminal untuk unit HM 400 sebanyak 1 unit

Before



After



5. Type Unit



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
A. B. P.	M. F. A. R. I. 2	cutimin
Ass Manager QA	Leader QA	Repairman