

LAPORAN MODIF KOMATSU INDONESIA

Tanggal Repair	18-Oct-24
Jam Berangkat	07.50 WIB
Jam Repair	09.40 s/d 17.05
Jam Kembali	20.15 WIB
Qty Unit Repair	1 pcs
Type Unit	PC 135 HARVESTER
Jumlah Man Power	1 Orang
Driver	-
Methode Repair	Potong wire ganti terminal dan pasang conector

Maker of Harness ☐ BEI ☒ NON BEI


Couse of Defect ☐ BEI ☒ NON BEI

MATERIAL UNTUK REPAIR :


PART NAME	PART NO	QTY
Terminal	1062-16-0122	8 Pcs
Terminal	1060-16-0122	8 Pcs
Terminal	+MT080-0123	2 Pcs
Terminal	+R1.25-5	1 Pcs
Terminal	+R1.25-8	1 Pcs
Wire	AVSS 0.5 B	1200 mm
Wire	AVSS 0.5 W	600 mm
Connector	DT06-6S-EP06	1 Pcs
Connector	DT04-6P-E005	1 Pcs
Retainer	W6P	1 Pcs
Retainer	W6S-P012	1 Pcs
Connector	+7124-9681	1 Pcs
Tape	WHVTA 19*20 B	200 mm
Fuse 10 A	+7123+3011	1 Pcs
Connector	DT04-2P-CE03	1 Pcs
Connector	DT06-2S-CE05	1 Pcs
Retainer	W2P	1 Pcs
Retainer	W2S-P012	1 Pcs
Terminal	B-1.25	8 Pcs

1.Modif PC 210 HARVESTER sebanyak 1 unit

BEFORE




AFTER



2.Sambung wire

Before




After




3.Pasang connector DT

Before



After



4.Type Unit



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
Ass Manager QA	Leader QA	Repairman