

LAPORAN REPAIR KOMATSU INDONESIA

Tanggal Repair	24-Jul-23
Jam Berangkat	08.10 WIB
Jam Repair	10.30 S/D 15.30
Jam Kembali	17.50 WIB
Qty Unit Repair	26 pcs
Assy No	14X06J1150-00
Type Unit	D85ESS-2 dan PC135F-10M0
Jumlah Man Power	1 Orang
Driver	1 Orang
Methode Repair	Potong Wire ganti terminal dan pasang connector

Maker of Harness ☒ BEI ☒ NON BEI

Couse of Defect ☐ BEI ☒ NON BEI


MATERIAL UNTUK REPAIR :

PART NAME	PART NO	QTY
Terminal	7116-2874	25 Pcs
Rubber seal	7157-2571-80	25 Pcs
Connector	7123-6214-40	25 Pcs
Connector	7222-7544-40	1 Pcs


1.Modif harness PC135F pada posisi AC03 dari connector DT ke connector 7123-6214-40 sebanyak 25 pcs



2.Ganti connector di assy 14X06J1150-00 posisi CN11



3.Type Unit



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
Asst Manager QA	Leader QA	Repairman