

LAPORAN REPAIR KOMATSU INDONESIA

Tanggal Repair	25-Aug-23
Jam Berangkat	07.50 WIB
Jam Repair	13.05 S/D 15.30
Jam Kembali	18.30 WIB
Qty Unit Repair	27 pcs
Assy No	-
Type Unit	PC135F-10M0 dan PC21 HARVESTER
Jumlah Man Power	2 Orang
Driver	-
Methode Repair	Potong Wire ganti terminal dan pasang connector

Maker of Harness ☐ BEI ☒ NON BEI


Couse of Defect ☐ BEI ☒ NON BEI

MATERIAL UNTUK REPAIR :



PART NAME	PART NO	QTY
Terminal	7116-2874	26 Pcs
Terminal	1062-16-0122	6 Pcs
Terminal	1060-16-0122	6 pcs
Rubber seal	7157-2571-80	26 Pcs
Connector	7123-6214-40	26 Pcs
Connector	DT06-6S-EP06	1 Pcs
Connector	DT04-6P-E005	1 Pcs
Retainer	W6P	1 Pcs
Retainer	W6S-P012	1 Pcs
Tape	WHVTA 19*20B	200 mm

1.Modif harness PC135F pada posisi AC03 dari connector DT ke connector 7123-6214-40 sebanyak 26 pcs

Before :




After :




2.Modif wire harness PC210 HARVESTER sebanyak 1 unit


Before :



After :



3.Type Unit



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
Asst Manager QA	Leader QA	Repairman