

LAPORAN REPAIR KOMATSU INDONESIA

Tanggal Repair	29-Sep-23
Jam Berangkat	09.15 WIB
Jam Repair	13.05 S/D 17.50
Jam Kembali	19.45 WIB
Qty Unit Repair	25 pcs
Assy No	22150615-00
Type Unit	PC135F-10M0
Jumlah Man Power	1 Orang
Driver	1 Orang
Methode Repair	Potong Wire ganti terminal dan pasang connector

Maker of Harness ☐ BEI ☒ NON BEI

Cause of Defect ☐ BEI ☒ NON BEI




MATERIAL UNTUK REPAIR :

PART NAME	PART NO	QTY
Terminal	7116-2874	25 Pcs
Rubber seal	7157-2571-80	25 Pcs
Connector	7123-6214-40	25 Pcs
Terminal	1062-16-0122	36 Pcs
Terminal	1060-16-0122	18 pcs
Connector	DT06-6S-EP06	3 Pcs
Connector	DT04-6P-E005	3 Pcs
Retainer	W6P	3 Pcs
Retainer	W6S-P012	3 Pcs



1. Modif harness PC135F pada posisi AC03 dari connector DT ke connector 7123-6214-40 sebanyak 25 pcs

Before :

After :



2. Assy No



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
Asst Manager QA	Leader QA	Repairman