

LAPORAN REPAIR KOMATSU INDONESIA

Tanggal Repair	12-Dec-23
Jam Berangkat	08.00 WIB
Jam Repair	10.35 S/D 16.10
Jam Kembali	18.40 WIB
Qty Unit Repair	35 pcs
Assy No	22150615-00
Type Unit	PC135F-10M0
Jumlah Man Power	1 Orang
Driver	1 Orang
Methode Repair	Potong Wire ganti terminal dan pasang connector

Maker of Harness ☐ BEI ☒ NON BEI



Couse of Defect ☐ BEI ☒ NON BEI

MATERIAL UNTUK REPAIR :


PART NAME	PART NO	QTY
Terminal	7116-2874	34 Pcs
Rubber seal	7157-2571-80	34 Pcs
Connector	7123-6214-40	34 Pcs
Terminal	MT080-01230	1 Pcs

1.Repair wire lepas 1 pcs

Before :






After :




2.Modif harness PC135F pada posisi AC03 dari connector DT ke connector 7123-6214-40 sebanyak 34 pcs

Before :



3.Assy No



4.Type Unit



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
Asst Manager QA	Leader QA	Repairman