

LAPORAN REPAIR KOMATSU INDONESIA

Tanggal Repair	04-Jan-24
Jam Berangkat	09.15 WIB
Jam Repair	11.25 S/D 15.30
Jam Kembali	17.56 WIB
Qty Unit Repair	24 pcs
Assy No	22150615-00
Type Unit	PC135F-10M0
Jumlah Man Power	1 Orang
Driver	
Methode Repair	Potong Wire ganti terminal dan pasang connector

Maker of Harness ☐ BEI ☒ NON BEI

Couse of Defect ☐ BEI ☒ NON BEI


MATERIAL UNTUK REPAIR :

PART NAME	PART NO	QTY
Terminal	7116-2874	24 Pcs
Rubber seal	7157-2571-80	24 Pcs
Connector	7123-6214-40	24 Pcs


1. Modif harness PC135F pada posisi AC03 dari connector DT ke connector 7123-6214-40 sebanyak 24 pcs

Before :

After :



2. Assy No



3. Type Unit



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
Asst Manager QA	Leader QA	Repairman