



Comment	Description	Designator	Footprint	LibRef	Quantity
MOVE-II PC104		H1	PC104	MOVE-II PC104	1
		STR1, STR2, T1, T2, T3,			
		T4, T5, T6, T7, T8, T9,			
		T10, T11, T12, T13, T14,			
		T15, T16, T17, T18, T19,			
		T20, T21, T22, T23, T24,			
		T25, T26, T27, T28, T29,			
		T30, T31, T32, T33, T34,			
		T35, T36, T37, T38, T39,			
		T40, T41, T42, T43, T44,			
		T45, T46, T47, T48, T49,			
		T50, T51, T52, T53, T54,			
		T55, T56, T57, T58, T59,			
		T60, T61, T62, T63, T64,			
		T65, T66, T67, T68, T69,			
		T70, T71, T72, T73, T74,			
		T75, T76, T77, T78, T79,			
		T80, T81, T82, T83, T84,			
		T85, T86, T87, T88, T89,			
		T90, T91, T92, T93, T94,			
		T95, T96, T97, T98, T99,			
		T100, T101, T102, T103,			
Testpoint	Plug	T104	PIN1	Plug	106