


WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT

Building No. 1634	Street Benedict Canyon Dr.	City Beverly Hills	Zip 90210	Date of Inspection 03/16/21	Number of Pages 6
 Family Exterminators 710 W. Dalton Ct. Upland CA 91784 Tel (800) 334-1811 Fax (877) 334-1812 familytermite@aol.com				Report # : 101916 Registration # : PR 3817 Escrow # : ☐ CORRECTED REPORT	
Ordered by: Ray Gastelum Ph. (213) 393-3670		Property Owner and/or Party of Interest:		Report sent to: Eduardo Umansky The Agency	
COMPLETE REPORT ☒ LIMITED REPORT ☐ SUPPLEMENTAL REPORT ☐ REINSPECTION REPORT ☐					
GENERAL DESCRIPTION: 1-Story Family Dwelling, Stucco Construction, Attached Garage, Detached Pool House and Gazebo with Roll Composition Roof.				Inspection Tag Posted: Attic Other Tags Posted:	
An inspection has been made of the structure(s) shown on the diagram in accordance with the Structural Pest Control Act. Detached porches, detached steps, detached decks and any other structures not on the diagram were not inspected.					
Subterranean Termites ☐ Drywood Termites ☒ Fungus / Dryrot ☒ Other Findings ☒ Further Inspection ☒ If any of the above boxes are checked, it indicates that there were visible problems in accessible areas. Read the report for details on checked					

Diagram Not To Scale



Inspected By: **Thomas Pemberton**

State License No. **OPR 8365**

Signature:



You are entitled to obtain copies of all reports and completion notices on this property reported to the Structural Pest Control Board during the preceding two years. To obtain copies contact: Structural Pest Control Board, 2005 Evergreen Street, Suite 1500, Sacramento, California, 95815-3831.

NOTE: Questions or problems concerning the above report should be directed to the manager of the company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control Board at (916) 561-8708, (800) 737-8188 or www.pestboard.ca.gov. 43M-41 (Rev. 10/01)

Family Exterminators

Page 2 of inspection report

1634	Benedict Canyon Dr.	Beverly Hills	CA	90210
Address of Property Inspected		City	State	Zip
	03/16/21	101916		
Stamp No.	Date of Inspection	Co. Report No.	Escrow No.	

WHAT IS A WOOD DESTROYING PEST & ORGANISM INSPECTION REPORT? READ THIS DOCUMENT. IT EXPLAINS THE SCOPE AND LIMITATIONS OF A STRUCTURAL PEST CONTROL INSPECTION AND A WOOD DESTROYING PEST & ORGANISM INSPECTION REPORT.

A Wood Destroying Pest & Organism Inspection Report contains findings as to the presence or absence of evidence of wood destroying pests and organisms in visible and accessible areas and contains recommendations for correcting any infestations or infections found. The contents of Wood Destroying Pest & Organism Inspection Reports are governed by the Structural Pest Control Act and regulations.

Some structures do not comply with building code requirements or may have structural, plumbing, electrical, mechanical, heating, air conditioning or other defects that do not pertain to wood destroying organisms. A Wood Destroying Pest & Organism Inspection Report does not contain information on such defects, if any, as they are not within the scope of the licenses of either this company, or it's employees.

The Structural Pest Control Act requires inspection of only those areas which are visible and accessible at the time of inspection. Some areas of the structure are not accessible to inspection, such as the interior of hollow walls, spaces between floors, areas concealed by carpeting, appliances, furniture or cabinets. Infestations or infections may be active in these areas without visible and accessible evidence. If you desire information about areas that were not inspected, a further inspection may be performed at an additional cost. Carpets, furniture or appliances are not moved and windows are not opened during a routine inspection.

The exterior Surface of the roof was not inspected. If you want the water tightness of the roof determined, you should contact a roofing contractor who is licensed by the Contractor's State License Board.

This company does not certify or guarantee against any leakage, such as (but not limited to) plumbing, appliances, walls, doors, windows, any type of seepage, roof or deck coverings. This company renders no guarantee, whatsoever, against any infection, infestation or any other adverse condition which may exist in such areas or may become visibly evident in such area after this date. Upon request, further inspection of these areas would be performed at an additional charge.

In the event damage or infestation described herein is later found to extend further than anticipated, our bid will not include such repairs. **OWNER SHOULD BE AWARE OF THIS CLOSED BID WHEN CONTRACTING WITH OTHERS OR UNDERTAKING THE WORK HIMSELF/HERSELF.**

If requested by the person ordering this report, a re-inspection of the structure will be performed. Such requests must be within four (4) months of the date of this inspection. Every re-inspection fee amount shall not exceed the original inspection fee.

Wall paper, stain, or interior painting are excluded from our contract. New wood exposed to the weather will be prime painted, only upon request at an additional expense.

This company will reinspect repairs done by others within four months of the original inspection. A charge, if any, can be no greater than the original inspection fee for each reinspection. The reinspection must be done within ten (10) working days of request. The reinspection is a visual inspection and if inspection of concealed areas is desired, inspection of work in progress will be necessary. Any guarantees must be received from parties performing repairs.

“NOTICE: Reports on this structure prepared by various registered companies should list the same findings (i.e. termite infestations, termite damage, fungus damage, etc.). However, recommendations to correct these findings may vary from company to company. You have a right to seek a second opinion from another company.”

This Wood Destroying Pest & Organisms Report DOES NOT INCLUDE MOLD or any mold like conditions. No reference will be made to mold or mold-like conditions. Mold is not a Wood Destroying Organism and is outside the scope of this report as defined by the Structural Pest Control Act. If you wish your property to be inspected for mold or mold like conditions, please contact the appropriate mold professional.

Family Exterminators

Page 3 of 6 of Standard Inspection Report

1634	Benedict Canyon Dr.	Beverly Hills	CA	90210
Address of Property Inspected		City	State	Zip
Stamp No.	03/16/21	101916		
	Date of Inspection	Co. Report No.	Escrow No.	

SECTION 1 CONTAINS ITEMS WHERE THERE IS EVIDENCE OF ACTIVE INFESTATION, INFECTION OR CONDITIONS THAT HAVE RESULTED IN OR FROM INFESTATION OR INFECTION.

SECTION 2 ITEMS ARE CONDITIONS DEEMED LIKELY TO LEAD TO INFESTATION OR INFECTION BUT WHERE NO VISIBLE EVIDENCE OF SUCH WAS FOUND.

FURTHER INSPECTION ITEMS ARE DEFINED AS RECOMMENDATIONS TO INSPECT AREA(S) WHICH DURING THE ORIGINAL INSPECTION DID NOT ALLOW THE INSPECTOR ACCESS TO COMPLETE HIS INSPECTION AND CANNOT BE DEFINED AS SECTION 1 OR 2.

1. SUBSTRUCTURE AREA:

01A - FINDING - Faulty planter and water damage found at front right same wall on interior. 1A on diagram.

RECOMMENDATION - Tradesman to repair as necessary. SECTION 1

01B - FINDING - Cellulose debris found in sub area. 1B on diagram.

RECOMMENDATION - Remove cellulose debris as necessary. SECTION 2

01C - FINDING - Plumbing leak found at drain line. 1C on diagram.

RECOMMENDATION - Tradesman to repair as necessary. SECTION 2

01D - FINDING - Evidence of drywood termites found in jams. 1D on diagram.

RECOMMENDATION - Chemically treat with TERMIDOR SC. Cover or remove pellets. SECTION 1

01E - FINDING - Drywood termite damage found in jams. 1E on diagram.

RECOMMENDATION - Repair as necessary. SECTION 1

01F - FINDING - Dryrot found at jams. 1F on diagram.

RECOMMENDATION - Repair as necessary. SECTION 1

01G - FINDING - Faulty planter in rear and left of property. 1G on diagram,

RECOMMENDATION - Tradesman to repair as necessary. SECTION 2

01H - FINDING - Inaccessible area of substructure due to grading. 1H on diagram.

RECOMMENDATION - Tradesman to lower dirt (make accessible) to allow inspection to be performed and a supplemental report to be issued as to findings and cost, if any.

2. STALL SHOWER:

NOTE - First floor shower was water tested, no leaks.

3. FOUNDATIONS: Raised

7. ATTIC SPACES: Insulated

07A - FINDING - Soft spots found on roof, unable to tell if loose roof or warped wood. 7A on diagram.

Family Exterminators

Page 4 of 6 of Standard Inspection Report

1634	Benedict Canyon Dr.	Beverly Hills	CA	90210
Address of Property Inspected		City	State	Zip
Stamp No.	03/16/21	101916		
Date of Inspection		Co. Report No.	Escrow No.	

RECOMMENDATION - Roofer to inspect and repair as necessary.

NOTE - Attic partially inaccessible due to insulation and ducts. N7 on diagram.

8. GARAGES:

08A - FINDING - Water appears to be seeping through roof. 8A on diagram.

RECOMMENDATION - Roofer to inspect and repair as necessary. SECTION 2

10. OTHER - POOL HOUSE:

10A - FINDING - Pool house appears to be faulty grade. 10A on diagram,

RECOMMENDATION - Tradesman to repair as necessary. SECTION 2

NOTES:

NOTE - Cracks found in stucco. N1 on diagram.

NOTE - Water staining found in stucco. N2 on diagram.

NOTE - Areas of ceiling appear to have been patched prior to inspection. N3 on diagram.

NOTE - Deterioration rs need to sign fumigation notices. N4 on diagram.

NOTE - "This property was not inspected for the presence or absence of health related molds or fungi. By California law we are neither qualified, authorized nor licensed to inspect for health related molds or fungi. If you desire information about the presence or absence of health related molds, you should contact an industrial hygienist." AMERICAN BOARD OF INDUSTRIAL HYGIENE...(517) 321-2638 OR <http://www.abih.org/> N5 on diagram.

NOTE - No drains found in planters.

COSTS:

Inspection Fee.....	PAID
Chemical Treatment (1D).....	\$ 450.00
Termite Damage and Dryrot (1E & 1F).....	325.00
Cellulose Debris (1B).....	450.00
Faulty Planters, Water Damage, Plumbing Leak and Inaccessible Area (1A, 1C, 1G, 1H & 11A)....	TRADESMAN
Seeping Water and Soft Spots-Roof (7A & 8A)..	ROOFER

Under no circumstance should this wood destroying pest and organisms inspection report be construed as a guarantee and/or warranty of the structure(s). Inspection reports are intended to disclose infestations, infections and /or conducive conditions which are noted on the date of the inspection in the visible and accessible areas only, as required by the Structural Pest Control Act. Any infestation, infections and/or conducive condition which are found after the date of inspection of any other person(s) will require an additional inspection report with findings, recommendation, and estimates.

A. Certain areas are recognized by the industry as inaccessible and/or for other reasons not inspected. These

Family Exterminators

Page 5 of 6 of Standard Inspection Report

1634	Benedict Canyon Dr.	Beverly Hills	CA	90210
Address of Property Inspected		City	State	Zip
03/16/21		101916		
Stamp No.	Date of Inspection	Co. Report No.	Escrow No.	

include, but are not limited to: Inaccessible and/or insulated attics or portions thereof, attics with less than 18" clear crawl space, the interior of hollow walls; spaces between a floor or porch deck and the ceiling below; area where there is no access without defacing or tearing out lumber, masonry or finished work; areas behind stoves, refrigerators or beneath floor coverings; furnishing; areas where encumbrances and storage; conditions or locks make inspection impractical, portions of the substructure concealed or make inaccessible by ducting or insulation, area beneath wood floors over concrete, and areas concealed by heavy vegetation. Areas or timbers around eaves were visually inspected from ground level only.

B. Slab floor construction has become more prevalent in recent year. Floor covering may conceal cracks in the slab that will allow infestation to enter. Infestations in the walls may be concealed by plaster so that a diligent inspection may not disclose the true condition. These areas are not practical to inspect because of health hazards, damage to the structure or inconvenience. They were not inspected unless described in this report. We recommend further inspection if there is any question about the above noted areas. Ref: Structural Pest Control Act, Article 6, Section 8516 (b), paragraph 1990 (1). Amended effective March 1, 1974. Inspection is limited to disclosure of wood destroying pests or organisms as set forth in the Structural Pest Control Act, Article 6, Section 8516 (b), Paragraph 1990-1991.

C: This inspection pertains only to the specific address or addresses indicated above and does not include any attached or adjacent unit (s).

D: A RE-INSPECTION WILL BE PERFORMED, IF REQUESTED WITH FOUR (4) MONTHS FROM DATE OF ORIGINAL INSPECTION, ON ANY CORRECTIVE WORK THAT WE ARE REGULARLY IN THE BUSINESS OF PERFORMING. IF CERTIFICATION IS REQUIRED, THEN ANY WORK PERFORMED BY OTHERS MUST BE CERTIFIED BY THEM. THERE IS A RE-INSPECTION FEE. FAMILY EXTERMINATORS DOES NOT GUARANTEE WORK DONE BY THE HOMEOWNER OR ANY OTHER COMPANY UNLESS SPECIFICALLY SUB-CONTRACTED BY FAMILY EXTERMINATORS.

E: This proposal does not include painting or decorating in the process of work performed. Items recommended will be replaced as close as possible to the original but are not guaranteed to match.

F: Second story stall showers are inspected, but not water tested unless there is evidence of leaks in ceiling below. Ref: Structural Pest Control Rules and Regulations, Sec. 1991(12). Sunken or below grade showers or tubs are not water tested due to their construction.

G: During the course of opening walls or any previously concealed areas, should any further damage or infestation be found, a supplementary report will be issued. Any work completed in these areas would be at owner's direction and additional expense.

H: During the process of treatment of replacement if may be necessary to drill holes through ceramic tiles or other floor coverings; these holes will then be sealed with concrete. We will exercise due care but assume no responsibility for cracks, chipping or other damage to floor coverings. We do not re-lay carpeting.

I: When a fumigation is recommended, we will exercise all due care, but assume no responsibility for damage to shrubs, trees, plants, TV antennas or roofs. An Occupant's Fumigation Notice and Disclaimer will be provided to the owner of the property of his/her designated agent. Occupant must comply with instructions contained in the Occupant's Fumigation Notice and Disclaimer. During fumigation and aeration, the possibility of burglary exists as it does any time you leave your home. Therefore, we recommend that you contact your insurance agent and verify that you have insurance coverage to protect against any loss, damage, or vandalism to your property. This company does not provide any onsite security except as required by state or local ordinance and does not assume any responsibility for care and custody of the property in case of vandalism, breaking or entering.

J: Your termite report and clearance will cover EXISTING infestation or infection which is outlined in this report.

K: If you have any questions regarding this report, please call our office any weekday between 8:00 a.m. and 5:00 p.m.

L: A visual inspection was performed and the inspector did not PROBE into finished window or door frames, trim boards, etc. unless there was visible evidence of infestation and/or infection. We do not inspect fences and gates.

NOTICE TO OWNER

Under the California Mechanics Lien Law, any structural pest control operator who contracts to do work for you, any contract, subcontractor, laborer, supplier or other person who helps to improve your property, but is not paid for this work or supplies, has a right to enforce a claim against your property. This means that, after a court hearing, the court officer could sell your property, and proceeds of the sale used to satisfy the indebtedness.

"State law requires that you be given the following information: CAUTION - PESTICIDES ARE TOXIC CHEMICALS. Structural Pest Control Companies are registered and regulated by the Structural Pest Control Board, and apply pesticides which are registered and approved for use by the California Department of Pesticide Regulation and the United States Environmental Protection Agency. Registration is granted when the state finds that, based on existing scientific evidence, there are no appreciable risks if proper use conditions are followed or that the risks are outweighed by the benefits. The degree of risk depends upon the degree of exposure, SO EXPOSURE SHOULD BE MINIMIZED."

"If within 24 hours following application you experience symptoms similar to common seasonal illness comparable to the flu, contact your physician or poison control center (800) 876-4766 and your pest control company immediately."

Family Exterminators

Page 6 of 6 of Standard Inspection Report

1634	Benedict Canyon Dr.	Beverly Hills	CA	90210
Address of Property Inspected		City	State	Zip
Stamp No.	03/16/21	101916		
Date of Inspection		Co. Report No.	Escrow No.	

For further information, contact any of the following:

Family Exterminators.....(800) 334-1811/(909) 946-0045

Poison Control Center.....(800) 876-4766

For Health Questions:

Los Angeles.....(800) 427-8700

Long Beach.....(562) 570-4132

San Bernardino.....(800) 722-4777

Riverside.....(951) 358-5000

Orange.....(714) 834-7700

County Agriculture Commission

For Application Information:

Los Angeles.....(626) 575-5466

San Bernardino.....(909) 387-2105

Riverside.....(951) 955-3000

Orange.....(714) 447-7100

Structural Pest Control Board

Regulatory Information:

2005 Evergreen St., Suite 1500

Sacramento, CA 95815-3831.....(800) 737-8188/(916) 561-8704

TERMITE AND FUNGUS CONTROL CHEMICALS:

For Fumigation Tenting Treatment:

Vikane (EPA Reg. No. 62719-4

Active Ingredients: Vikane-sulfuryl floride 99.5%, Chloropicrin 5% (Tear Gas)

For Manual Chemical Treatment:

Termidor HE....(EPA Reg. 499-552-7969)

Active Ingredients: Fipronil: 5-amino-[2,6 dichloro-4-(trifluoromethyl)phenyl]

-4-[(1R,S)-(trifluoromethyl)sulfinyl]-1H-pyrazole-3-carbonitrile.....9.1%

Timbor.....(EPA Reg. No. 1624-39)

Active Ingredients: Disodium Octaborate Tetrahydrate...98%

PLEASE KEEP IN MIND THAT THE ABOVE IS FOR YOUR INFORMATION AND BE ASSURED THAT THE UPMOST CARE WILL BE USED AT ALL TIMES WHEN BEING SERVICED BY FAMILY EXTERMINATORS. OUR EMPLOYEES ARE LICENSED AND INSTRUCTED ON THE USE OF THESE CHEMICALS AND CAUTION IS USED AT ALL TIMES WHEN SERVICING YOUR HOME.