


WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT

Building No. 139	Street S. Edinburgh Ave.	City Los Angeles	ZIP 90048	Date of Inspection 05/13/2025	Number of Pages 5
		Jacob Termite & Pest Control Inc. PO Box 74160 Los Angeles CA 90004 (213) 700-7316 jacobpestcontrol@gmail.com		Report # : 912549 Registration # : PR7826 Escrow # : ☐ CORRECTED REPORT	
Ordered by: Michael Zargarian Next Home Grandview		Property Owner and Party of Interest:		Report sent to:	
COMPLETE REPORT ☒ LIMITED REPORT ☐ SUPPLEMENTAL REPORT ☐ REINSPECTION REPORT ☐					
GENERAL DESCRIPTION: Two-story single family residence, frame & stucco, flat roof, furnished & occupied, attached garage, header construction				Inspection Tag Posted: Subarea Other Tags Posted: N/A	
An inspection has been made of the structure(s) shown on the diagram in accordance with the Structural Pest Control Act. Detached porches, detached steps, detached decks and any other structures not on the diagram were not inspected.					
Subterranean Termites ☐ Drywood Termites ☒ Fungus / Dryrot ☐ Other Findings ☒ Further Inspection ☒					
If any of the above boxes are checked, it indicates that there were visible problems in accessible areas. Read the report for details on checked items.					

Diagram Not To Scale



Inspected By: Jacob Kim State License No. OPR13204 Signature: 

You are entitled to obtain copies of all reports and completion notices on this property reported to the Structural Pest Control Board during the preceding two years. To obtain copies contact: Structural Pest Control Board, 2005 Evergreen Street, Suite 1500, Sacramento, California, 95815-3831.
 NOTE: Questions or problems concerning the above report should be directed to the manager of the company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control Board at (916) 561-8708, (800) 737-8188 or www.pestboard.ca.gov.
 43M-41 (Rev. 04/2015)

JACOB TERMITE & PEST CONTROL INC.

Page 2 of 5 inspection report

139	S. Edinburgh Ave.	Los Angeles	CA	90048
Address of Property Inspected		City	State	ZIP
05/13/2025	912549			
Date of Inspection		Corresponding Report No.		Escrow No.

WHAT IS A WOOD DESTROYING PEST & ORGANISM INSPECTION REPORT? READ THIS DOCUMENT. IT EXPLAINS THE SCOPE AND LIMITATIONS OF A STRUCTURAL PEST CONTROL INSPECTION AND A WOOD DESTROYING PEST & ORGANISM INSPECTION REPORT.

A Wood Destroying Pest & Organism Inspection Report contains findings as to the presence or absence of evidence of wood destroying pests and organisms in visible and accessible areas and contains recommendations for correcting any infestations or infections found. The contents of Wood Destroying Pest & Organism Inspection Reports are governed by the Structural Pest Control Act and regulations.

Some structures do not comply with building code requirements or may have structural, plumbing, electrical, mechanical, heating, air conditioning or other defects that do not pertain to wood destroying organisms. A Wood Destroying Pest & Organism Inspection Report does not contain information on such defects, if any, as they are not within the scope of the licenses of either this company, or it's employees.

The Structural Pest Control Act requires inspection of only those areas which are visible and accessible at the time of inspection. Some areas of the structure are not accessible to inspection, such as the interior of hollow walls, spaces between floors, areas concealed by carpeting, appliances, furniture or cabinets. Infestations or infections may be active in these areas without visible and accessible evidence. If you desire information about areas that were not inspected, a further inspection may be performed at an additional cost. Carpets, furniture or appliances are not moved and windows are not opened during a routine inspection.

The exterior Surface of the roof was not inspected. If you want the water tightness of the roof determined, you should contact a roofing contractor who is licensed by the Contractor's State License Board.

This company does not certify or guarantee against any leakage, such as (but not limited to) plumbing, appliances, walls, doors, windows, any type of seepage, roof or deck coverings. This company renders no guarantee, whatsoever, against any infection, infestation or any other adverse condition which may exist in such areas or may become visibly evident in such area after this date. Upon request, further inspection of these areas would be performed at an additional charge.

In the event damage or infestation described herein is later found to extend further than anticipated, our bid will not include such repairs. OWNER SHOULD BE AWARE OF THIS CLOSED BID WHEN CONTRACTING WITH OTHERS OR UNDERTAKING THE WORK HIMSELF/HERSELF.

If requested by the person ordering this report, a re-inspection of the structure will be performed. Such requests must be within four (4) months of the date of this inspection. Every re-inspection fee amount shall not exceed the original inspection fee.

Wall paper, stain, or interior painting are excluded from our contract. New wood exposed to the weather will be prime painted, only upon request at an additional expense.

This company will reinspect repairs done by others within four months of the original inspection. A charge, if any, can be no greater than the original inspection fee for each reinspection. The reinspection must be done within ten (10) working days of request. The reinspection is a visual inspection and if inspection of concealed areas is desired, inspection of work in progress will be necessary. Any guarantees must be received from parties performing repairs.

NOTICE: Reports on this structure prepared by various registered companies should list the same findings (i.e. termite infestations, termite damage, fungus damage, etc.). However, recommendations to correct these findings may vary from company to company. You have a right to seek a second opinion from another company.

This Wood Destroying Pest & Organisms Report DOES NOT INCLUDE MOLD or any mold like conditions. No reference will be made to mold or mold-like conditions. Mold is not a Wood Destroying Organism and is outside the scope of this report as defined by the Structural Pest Control Act. If you wish your property to be inspected for mold or mold like conditions, please contact the appropriate mold professional.

JACOB TERMITE & PEST CONTROL INC.

Page 3 of 5 inspection report

139	S. Edinburgh Ave.	Los Angeles	CA	90048
Address of Property Inspected		City	State	ZIP
05/13/2025	912549			
Date of Inspection	Corresponding Report No.	Escrow No.		

THIS IS A SEPARATED REPORT WHICH IS DEFINED AS SECTION I/SECTION II CONDITIONS EVIDENT ON THE DATE OF THE INSPECTION.

SECTION I CONTAINS ITEMS WHERE THERE IS EVIDENCE OF ACTIVE INFESTATION, INFECTION OR CONDITIONS THAT HAVE RESULTED IN OR FROM INFESTATION OR INFECTION.

SECTION II ITEMS ARE CONDITIONS DEEMED LIKELY TO LEAD TO INFESTATION OR INFECTION BUT WHERE NO VISIBLE EVIDENCE OF SUCH WAS FOUND.

FURTHER INSPECTION ITEMS ARE DEFINED AS RECOMMENDATIONS TO INSPECT AREA(S) WHICH DURING THE ORIGINAL INSPECTION DID NOT ALLOW THE INSPECTOR ACCESS TO COMPLETE HIS INSPECTION AND CANNOT BE DEFINED AS SECTION I OR II.

2. DRYWOOD TERMITES:

2A - Section I

FINDING: Evidence of drywood termites extending to inaccessible areas was noted in the subarea, 2A on the diagram..

PRIMARY RECOMMENDATION: Fumigate the structure with a state approved and registered fumigant to control drywood termites. Owner or agent to prepare the structure for fumigation as per list of instructions to be furnished by this company. The structure must be vacated until released for re-entry by the licensed fumigator. Cover evidence as necessary. (2 year guarantee)

4. OTHER FINDINGS:

4A - Section II

FINDING: Cellulose debris (wood, paper products) was noted in the subarea, 4A on the diagram.

RECOMMENDATION: Owner/agent should engage the services of a licensed contractor to remove all cellulose debris of a size that can be raked (or larger)

4B - Section II

FINDING: Form boards/stakes were noted embedded in the subarea soil, 4B on the diagram.

RECOMMENDATION: Owner/agent should engage the services of a licensed contractor to remove and dispose of the form boards/stakes from the subarea.

5. FURTHER INSPECTION:

5A - Further Inspection

FINDING: The garage is partially inaccessible for inspection due to occupant's storage where indicated on diagram.

RECOMMENDATION: The owner should remove the storage where indicated and call for further inspection. For an additional charge (not to exceed the cost of the original inspection) the garage will be inspected and any findings will be listed on a supplemental report along with estimates for repair and/or treatment, if within the scope of this company's operations.

NOTES:

Note A

Jacob Termite & Pest Control Inc. guarantees all repair work performed by this company for one-year, local treatment for one-year, and fumigations are guaranteed for two-years. This company is not responsible for any future infestation, dry rot or adverse conditions beyond the time of inspection. if fumigation is performed, Jacob Termite & Pest Control Inc. is not liable for any damage to shrubs, vines, trees, etc. or any damage to roofs or roof members at the time of fumigation. In the event that a re-treatment, re-fumigation or any other repair work is to be performed to honor a guarantee issued by Jacob Termite & Pest Control Inc. the home-owner is responsible to make the property available for any work to be performed. Jacob Termite & Pest Control Inc. will not be liable for any cost of vacating or preparing the residence for re-treatment and/or repairs. Note: A new

JACOB TERMITE & PEST CONTROL INC.

Page 4 of 5 inspection report

139	S. Edinburgh Ave.	Los Angeles	CA	90048
Address of Property Inspected		City	State	ZIP
05/13/2025	912549			
Date of Inspection	Corresponding Report No.	Escrow No.		

and/or extension of guarantee is never given for re-treatment done under original guarantee.

Any wood members that can not be inspected due to height limitations which is a health hazard to this inspector using a standard six-foot ladder and due to strict compliance of the workman's compensation requirements of this company. This company is not responsible for any wood destroying organism found by others on any wood members that would require the use of an extension ladder.

Local treatment is not intended to be an entire structure treatment method. If infestations of wood-destroying pests or exist beyond the area(s) of local treatment, they may not be exterminated.

The following areas are considered inaccessible for purposes of inspection or are not included in a normal inspection report and therefore are excluded in this report: the interior of hollow walls; spaces between an upstairs floor and the ceiling below or a porch deck and soffit below; stall showers on slab; stall showers with no dam; stall showers over finished ceilings; such structural segments as areas enclosed by bay windows, buttresses, built in cabinet work, areas under floor covering; any areas requiring the removal of storage, furnishings or appliances; any areas to which there is no access without defacing or removing lumber, masonry or finished workmanship.

Certain areas are recognized by the industry as inaccessible and/or for other reasons not inspected. These include but are not limited to: inaccessible and/or, insulated attics or portions thereof, attics with less than 18" clear crawl space, the interior of hollow walls; spaces between a floor or porch deck and the ceiling below; areas where there is no access without defacing or tearing out lumber, masonry or finished work; make inspection impractical; and areas or timbers around eaves that would require use of an extension ladder.

Certain areas may be inaccessible for inspection due to construction or storage. We recommend further inspection of areas where inspection was impractical. Re: Structural Pest Control Act, Article 6, section 8516 (b), paragraph 1990 (I). Amended effective March 1, 1974. Stall shower, if any, are water tested in compliance with Section 1991 (12) of the Structural Pest Control Act. The absence or presence of leaks through sub-floor, adjacent floors or walls will be reported. This is a report of the condition of the stall shower at the time of inspection only, and should not be confused as a guarantee. Although we make a visual examination, we do not deface or probe into window or door frames, decorative trim, roof members, etc., in search of wood destroying pests or organisms.

Thank you for selecting us to perform a structural pest control inspection on your property. Should you have any questions regarding this report, please call us directly by the contact information provided on the first page of the inspection report.

Our inspectors have determined that your property will benefit from a safe application of chemicals commonly used for structural pest control. In accordance with the laws and regulations of the State of California, we are required to provide you and your occupants with the following information prior to any application of chemicals to such property.

Please take a few moments to read and become familiar with the content. State law requires that you be given the following information:

CAUTION - PESTICIDES ARE TOXIC CHEMICALS. Structural pest control companies are registered and regulated by the Structural Pest Control Board, and apply pesticides which are registered and approved for use by the California Department of Food and Agriculture and the United States Environmental Protection Agency. Registration is granted when the state finds that based on scientific evidence, there are no appreciable risks weighted by the benefits. The degree of risk depends on the degree of exposure, so exposure should be minimized.

If within 24 hours following application, you experience symptoms similar to common seasonal illness comparable to the flu, contact your physician or poison control center and your pest control operator immediately.

The chemical information as follows:

BORA-CARE (EPA Reg.No. 64405-1)

JACOB TERMITE & PEST CONTROL INC.

Page 5 of 5 inspection report

139	S. Edinburgh Ave.	Los Angeles	CA	90048
Address of Property Inspected		City	State	ZIP
05/13/2025	912549			
Date of Inspection	Corresponding Report No.	Escrow No.		

Active Ingredients: Disodium Octaborate Tetrahydrate 40%

TIMBOR (EPA Reg. No. 1624-39)

Active Ingredients: Disodium Octaborate Tetrahydrate 98%

TERMIDOR (EPA Reg.No. 432-901)

Active Ingredients: Fipronil 9.1%

FOR FUMIGATION

VIKANE (EPA Reg.No. 464-232)

Active Ingredients: Vikane-Sulfuryl Floride 99.0%, Chloropicrin 1%

For further information, contact any of the following agencies in your area:

Poison Control Center	(800) 222-1222
Agricultural Department	(626) 575-5471
Health Department	(213) 989-7140
Structural Pest Control Board	(916) 561-8700
	2005 Evergreen Street, Ste. 1500. Sacramento, CA 95815
Jacob Termite & Pest Control Inc.	(213) 700-7316



Jacob Termite & Pest Control Inc.

PO Box 74160
Los Angeles CA 90004
(213) 700-7316
jacobpestcontrol@gmail.com

Page 1 of 1

WORK AUTHORIZATION

Report #: 912549

No work will be performed until a signed copy of this agreement has been received.

Address of Property : 139 S. Edinburgh Ave.

City: Los Angeles

State/ZIP: CA 90048

The inspection report of the company dated, **05/13/2025** is incorporated herein by reference as though fully set forth.

The company is authorized to proceed with the work outlined in the items circled below from the Termite Inspection Report for the property inspected, for a total sum of \$ _____. This total amount is due and payable within 30 days from completion repair work and/or chemical application.

THE COMPANY AGREES

To guarantee all repair completed by this company for one year from date of completion except for caulking, grouting, or plumbing, which is guaranteed for a period of **ninety (90) days**. We assume no responsibility for work performed by others, to be bound to perform this work for the price quoted in our cost breakdown for a period not to exceed 30 days, to use reasonable care in the performance of our work but to assume no responsibility for damage to any hidden pipes, wiring, or other facilities or to any shrubs, plants, or roof.

THE OWNER OR OWNER'S AGENT AGREES

To pay for services rendered in any additional services requested upon completion of work to pay a service charge of one and one-half percent (1 1/2%) interest per month, or portion of any month, annual interest rate of eighteen percent (18%) on accounts exceeding the ten (10) day full payment schedule. The Owner grants to The Company a security interest in the property to secure payment sum for work and inspection fee completed. In case of non-payment by The owner, reasonable attorney fees and costs of collection shall be paid by owner, whether suit be filed or not.

ALL PARTIES AGREE

If any additional work is deemed necessary by the local building inspector, said work will not be performed without additional authorization from owner or owner's agent. This contract price does not include the charge of any Inspection Report fees. Circle the items you wish performed by The Company, below and enter total amount above:

NOTICE TO OWNER

Under the California Mechanics Lien Law, any structural pest control company which contracts to do work for you, any contractor, subcontractor, laborer, supplier or other person who helps to improve your property, but is not paid for his or her work or supplies, has a right to enforce a claim against your property. This means that after a court hearing, your property could be sold by a court officer and the proceeds of the sale used to satisfy the indebtedness. This can happen even if you have paid your structural pest control company in full if the subcontractor, laborers or suppliers remain unpaid.

To preserve their right to file a claim or lien against your property, certain claimants such as subcontractors or material suppliers are required to provide you with a document entitled "Preliminary Notice." Prime contractors and laborers for wages do not have to provide this notice. A Preliminary Notice is not a lien against your property. Its purpose is to notify you of persons who may have a right to file a lien against your property if they are not paid.

ITEMS

Prefix	Section I	Section II	Further Inspection	Other
2A	3,755.00	0.00	0.00	0.00
4A	0.00	see contractor	0.00	0.00
4B	0.00	see contractor	0.00	0.00
5A	0.00	0.00	0.00	0.00
Total:	3,755.00	0.00	0.00	0.00
GRAND TOTAL:	3,755.00			

Property Owner/Buyer/Seller:

Date:

Inspected By:

Date:

Agent:

Date: