

REAL ESTATE INFORMATION NETWORK, INC.
PROPERTY INSPECTION CONTINGENCY REMOVAL ADDENDUM



This document forms an integral part of the Purchase Agreement ("Agreement") dated 01/12/2026,
between Diane Nwaonicha ("Buyer")
Jemal Tamem ("Seller")
Berkshire Hathaway HomeServices RW Towne Realty ("Selling Firm")
and AtCoastal Realty ("Listing Firm")
for the sale of certain property commonly known as (Address): 4232 Maplehurst Road, Virginia Beach, VA 23462

Subject to A or B below, the following property inspection contingencies are hereby removed and a complete copy of the applicable Inspection(s) is attached:

(Check As Applicable)

☒ Property Inspection ☐ EIFS ☐ Lead-Based Paint Assessment ☐ Other _____

Mark as appropriate: A or B

☐ (A) No repairs are necessary; OR

☒ (B) Requested Repair Items: Seller agrees to make all repairs listed below at Seller's expense. The total cost of Requested Repair Items agreed to be repaired by Seller shall not be included in the Cap referenced in Paragraph 13 of the Agreement, unless otherwise agreed to in writing. In the performance of an EIFS repair, Seller is to use a qualified professional with experience in this field. All repairs to be completed in a workmanlike manner prior to walk through and evidence of payment, if applicable, for such work shall be provided to Buyer prior to Walk-through.

Buyer, at Buyer's expense, reserves the right to have the original inspector/firm inspect such work upon completion. Such inspection may occur at or prior to the Walk-Through. Seller remains obligated to perform all obligations under Paragraph 12 of the Agreement. Furthermore, subject to the Cap, Seller remains obligated to repair any Waived Items that fall under Paragraph 13A (Appraisal and Required Repairs), B (Wood Destroying Insect Infestation / Moisture Inspection / Repairs) or C (Well and Septic) of the Agreement.

~~Flashings and Penetrations
4.1. Loose flashing (s) should be secured and sealed to prevent moisture intrusion. Location: power ventilator
Exterior
Vinyl Siding Item: 1 1.4. Damage to the vinyl siding which can allow moisture intrusion and should be repaired. Location: front middle
Eaves, Soffits, and Trim
3.4. Multiple trim issues were observed, examples are listed in the report. A qualified contractor should make all necessary repairs.
Exterior Doors
4.1. Damage to an exterior door should be repaired or replaced as needed. Location: shed
HVAC
Condensate Drain(s) 6.2. There was no auxiliary condensate drain line or float switch installed at the condensate pan and should be corrected to prevent moisture damage if pan fills with water.
Plumbing
Water Heater
6.3. Issues were observed with the water heater, examples are in the report. Due to the age of the water heater we recommend a qualified plumbing contractor determine if repair or replacement
7.1. A hose spigot that was leaking while turned off should be repaired. Location: front
8.1. Leaking faucet controls should be repaired as needed. Location: kitchen sink
9.2. Leaking sink should be repaired as needed. Location: kitchen sink, master bath sink
10.3. Leaking bathtub faucet controls should be repaired as needed. Location: master bathroom
10.4. There is damage to the bathroom tubs that should be repaired/replaced Location: Master & hall
12.2. A toilet ran continuously indicating the need for repair. Location: Upstairs hall bath~~

In lieu of any repairs, Buyer and Seller agree that Seller shall provide Buyer with a credit in the amount of \$2,000.00 to be applied toward Buyer's closing costs and/or prepaid expenses at settlement. No repairs shall be required of Seller.

Initial: Buyer

DN
01/20/26
8:52 AM EST
dotloop verified

Seller

PROPERTY INSPECTION CONTINGENCY REMOVAL ADDENDUM (Continued)

Subject Property: 4232 Maplehurst Road, Virginia Beach, VA 23462

Buyer: Diane Nwaonicha

Seller: Jemal Tamem

~~12.1 Tighten toilet-hall bath
11.1. Leaking shower heads should be tightened or sealed to prevent moisture damage. Location: Upstairs hall bath
11.2. Loose shower head(s) Location: upstairs hall bath, master bath
3.5. A clear and complete circuit directory should be installed, and circuit size verified for correct installation, so that in an emergency individual circuits can be quickly shut off. Label circuit panel.
3.4. Breaker(s) were off in the main electrical service panel -Have electrician evaluate breakers are functioning as they should, correct size, etc. since they have been turned off.
3.6. Rust or corrosion was present in the panel and a qualified electrical contractor should determine source of moisture and repair as needed.
9.2. There was a loose ceiling fan which should be repaired master bedroom
9.3. Improper installation of a light fixture in the living room should be repaired or removed (over living room windows)
2.1 Repair/replace attic light fixture
7.4. Multiple receptacles issues were observed. Have a licensed electrician evaluate/repair/replace ALL outlets (GFCI's where required) and switches as needed.
10.3. There was a central security panel present. We did not engage the smoke alarm test buttons in order to prevent causing a false alarm with a security company. Confirm all smoke alarms function as they should.
Interior and Property Information
Loose railing(s) at the stairs should be secured to provide safe conditions. Location: bottom and top of staircase
3.2. Bathroom fans terminated in the attic fan can allow moisture into the attic and cause damage to the fans. Properly reroute bath fan terminations.
6.2. There were indications of moisture intrusion evidenced by stained roof deck, but the location was not accessible to test. All necessary repairs should be made if not previously corrected. Location: rear left, front right, rear right. Have evaluated by licensed roofing contractor.
6.3. Damaged roof sheathing should be repaired as needed. Location: rear power ventilator, front left plumbing vent, right of ventilator, front right- Have evaluated by licensed roofing contractor.
4.1 Window: repair/replace Location: living room right
6.2 Repair doors to latch properly. Location: water heater closet, left living area closet
3.1-3.3-Dishwasher leaks, repair to make sure it functions as it should. Could not properly test due to personal items present
4.1. The disposal was inoperable and should be repaired/replaced
12.2. There were visible observations of environmental conditions which are outside the scope of a home inspection listed in the interior section under Environmental Observations. Have appropriate company evaluate for possible remediation.~~

~~*** All repairs to be made by licensed contractors in their fields,
*** Inspection to take place 5 days prior to closing.
*** All invoices to be shared prior to final walkthrough. All invoices are to have the license information for each contractor/company included.
*** Remove all trash/personal property not listed on items to convey from interior/exterior of property prior to final walkthrough. Thank you.~~

Received by: [Signature]

Berkshire Hathaway HomeServices RW Towne Realty
(Selling Firm)

By: *Bobbi Wood* dotloop verified 01/20/26 9:47 AM EST 2MGZ-VQEV-DOKT-PZIC
(Date)

AtCoastal Realty
(Listing Firm)

By: *[Signature]* Authentisign 01/24/2026
(Date)

Diane Nwaonicha dotloop verified 01/20/26 9:52 AM EST FCTM-QYUY-J2DD-JFLA
(Buyer) (Date)

[Signature] (Buyer) (Date)

Jemal O Tamem 01/24/2026
(Seller) (Date)

[Signature] (Seller) (Date)

(FOR AGENT USE ONLY)

FOR COMPLETION BY AGENT VERIFYING REMOVAL ACCEPTANCE DATE:

This Property Inspection Contingency Removal Addendum has been accepted by all parties as of _____ ("Removal Acceptance Date").

SIGNATURE: [Signature]

☐ LISTING AGENT ☐ SELLING AGENT

MOISTURE INSPECTION REPORT		
NAME & ADDRESS OF INSPECTION COMPANY Pest Heroes 2128 London Bridge Rd. Suite 103 Virginia Beach, VA 23456		ADDRESS OF PROPERTY INSPECTED 4232 Maplehurst Rd Virginia Beach, VA 23462
		DATE OF INSPECTION 2026-01-19 INSPECTION FEE 79.00
BASED ON A CAREFUL INSPECTION OF THE READILY ACCESSIBLE AREAS OF THE UNDERSTRUCTURE (AS DESCRIBED ON THE REVERSE SIDE) OF THE PROPERTY LISTED ABOVE:		
There is evidence of the presence of wood destroying fungi below the floor level of the first main floor.		YES ☐ NO ☐
There is evidence of the presence of excessive moisture conditions below the floor level of the first main floor. (If yes, describe under comments)		YES ☐ NO ☐
At the time of our inspection, there were visible damaged wooden members below the floor level of the first main floor caused by fungi.		YES ☐ NO ☐
IF ANY DAMAGE IS OBSERVED (AS SHOWN ABOVE) THAT DAMAGE WILL (CHECK ONE BELOW):		
☐ Be corrected or has been corrected by this company.		
☐ Be corrected by another company, see attached contract.		
☐ NOT be corrected by this company which recommends that damage be evaluated by a qualified building expert and that needed repairs be made.		
WERE ANY AREAS OF THE UNDERSTRUCTURE OBSTRUCTED OR INACCESSIBLE? (If yes, describe under comments)		YES ☒ NO ☐
COMMENTS House on slab no inspection below possible		
SIGNATURE OF INSPECTOR: 		
This report shall not be valid until the following statement of the property owner(s) or their duly authorized representatives is signed: THE UNDERSIGNED OWNER(S) OF THE ABOVE DESCRIBED INSPECTED PROPERTY HEREBY ACKNOWLEDGE THAT THEY ARE UNAWARE OF ANY PREVIOUS MOISTURE DAMAGE OR DIFFICULTIES INVOLVING MOISTURE THROUGHOUT THEIR OWNERSHIP OF SAID PROPERTY, OTHER THAN AS REPORTED ABOVE.		
DATE: 2026-01-19PROPERTY OWNER:  Jemal O Tamem 01/24/2026PROPERTY OWNER:		
ACKNOWLEDGEMENT: Purchaser acknowledges that he has received a copy of this report.		
DATE ACKNOWLEDGED: 2026-01-19 PURCHASER'S SIGNATURE:		

PLEASE NOTE THE FOLLOWING STATEMENTS:

1. The inspection covered only the readily accessible areas of the understructure including sills, joists, subflooring and substructure support timbers which were visible. It was made only in those areas which were readily accessible and was made in areas where moisture conditions were most likely to occur. No inspection was made in areas which required the breaking apart, dismantling or removal of any object and no inspection was made of any portion of the property other than the foundation and the understructure below the floor level of the first main floor.
2. If damage from moisture of fungi is discovered, it is the responsibility of the property owner to determine whether the damage requires repair by having a licensed building contractor or a structural engineer inspect and estimate the necessary repairs, or submit in writing that the damage does not warrant repair.
3. The inspection did not include areas which were obstructed or inaccessible at the time of inspection.
4. This report does not in any way relate to an inspection for infestation or damage from wood destroying insects. Results of any inspection for wood destroying insect infestation or damage is the subject of an entirely separate inspection and report which is in no way involved with the preparation of this report.
5. This report is not a guarantee against future moisture damage or moisture conditions, but is indicative of the conditions of the understructure on the date of inspection.
6. This is not a structural damage report. Neither is this a warranty as to the absence of moisture.
7. This report is not a comprehensive moisture report regarding the entire structure but only discloses the results of an inspection of the understructure as described in 1 above. Therefore, this report should not be relied upon in lieu of a physical inspection of the entire premises by any interested parties or persons.

Wood Destroying Insect Inspection Report

Notice: Please read important consumer information on **page 2**.

Section I. General Information

Inspection Company, Address & Phone

Pest Heroes

2128 London Bridge Rd. Suite 103

Virginia Beach, VA 23456

(757) 367-8342

Company's Pest Control Business Lic. No.

15611

Date of Inspection

2026-01-19

Address of Property Inspected

4232 Maplehurst Rd

Virginia Beach, VA 23462

Inspector's Name, Signature & Certification, Registration, or Lic. #

Scott cohen 91177c

Structure(s) Inspected

Shared wall townhouse w att shed

Section II. Inspection Findings

This report is indicative of the condition of the above identified structure(s) on the date of inspection and is not to be construed as a guarantee or warranty against latent, concealed, or future infestations or wood destroying insect damage. **Based on a careful visual inspection of the readily accessible areas of the structure(s) inspected:**

☒ A. **No Visible** evidence of wood destroying insects was observed.

☐ B. **Visible** evidence of wood destroying insects was observed.

☐ 1. Live insects (description & location):

☐ 2. Dead insects, insect parts, frass, shelter tubes, exit holes, or staining (description and location):

☐ 3. **Visible** damage from wood destroying insects was noted as follows (description and location):

NOTE: This is not a structural damage report. If box B above is checked, it should be understood that some degree of damage, including hidden damage, may be present. If any questions arise regarding damage indicated by this report, it is recommended that the buyer or any interested parties contact a qualified structural professional to determine the extent of damage and the need for repairs.

Section III. Recommendations

☒ No action and/or treatment recommended: (Explain if Box B in Section II is checked):

☐ Recommended action(s) and/or treatment(s) for the control of:

Section IV. Obstructions and Inaccessible Areas

The following areas of the structure(s) inspected were obstructed or inaccessible:

☐ Basement

☐ Crawlspace

☒ Main Level **13,4,9**

☐ Attic

☐ Garage

☒ Exterior **17**

☐ Porch

☐ Addition

☒ Other **Att shed 6,7,9,11**

The inspector may write out obstructions or use the following optional key:

- | | |
|-------------------------|--|
| 1. Fixed ceiling | 15. Standing water |
| 2. Suspended ceiling | 16. Dense vegetation |
| 3. Fixed wall covering | 17. Exterior siding |
| 4. Floor covering | 18. Window well covers |
| 5. Insulation | 19. Wood pile |
| 6. Cabinets or shelving | 20. Snow |
| 7. Stored items | 21. Unsafe conditions |
| 8. Furnishings | 22. Rigid foam board |
| 9. Appliances | 23. Synthetic stucco |
| 10. No access or entry | 24. Duct work, wiring, and/or plumbing |
| 11. Limited access | 25. Spray foam insulation |
| 12. No access beneath | 26. Equipment |
| 13. Only visual access | |
| 14. Cluttered condition | |

Section V. Additional Comments and Attachments (these are an integral part of the report)

Attachments **Moisture report invoice**

Signature of Seller(s) or Owner(s) if refinancing. Seller discloses to the buyer all information, to their knowledge, regarding W.D.I. infestation, damage, repair, and treatment history.

X **Jemal O Tamem**

01/24/2026

Signature of Buyer. The undersigned hereby acknowledges receipt of a copy of both page 1 and page 2 of this report and understands the information reported.

X

Important Consumer Information Regarding the Scope and Limitations of the Inspection

Please read this entire page as it is part of this report. Please refer to the NPMA Suggested Guidelines for instructions on completing this report. This report is not a guarantee or warranty as to the absence of wood destroying insects nor is it a structural integrity report. The inspector's training and experience do not qualify the inspector in damage evaluation or any other building construction technology and/or repair.

1. **About the Inspection:** A visual inspection was conducted in the readily accessible areas of the structure(s) indicated (see Page 1) including attics and crawlspaces which permitted entry during the inspection. The inspection included probing and/or sounding of unobstructed and accessible areas to determine the presence or absence of visual evidence of wood destroying insects. The WDI inspection firm is not responsible to repair any damage or treat any infestation at the structure(s) inspected, except as may be provided by separate contract. Also, wood destroying insect infestation and/or damage may exist in concealed or inaccessible areas. The inspection firm cannot guarantee that any wood destroying insect infestation and/or damage disclosed by this inspection represents all of the wood destroying insect infestation and/or damage which may exist as of the date of the inspection. **For purposes of this inspection, wood destroying insects include: termites, carpenter ants, carpenter bees, and reinfesting wood boring beetles. This inspection does not include mold, mildew or noninsect wood destroying organisms.** This report shall be considered invalid for purposes of securing a mortgage and/or settlement of property transfer if not used within ninety (90) days from the date of inspection. **This shall not be construed as a 90-day warranty.** There is no warranty, express or implied, related to this report unless disclosed as required by state regulations or a written warranty or service agreement is attached.
2. **Treatment Recommendation Guidelines Regarding Subterranean Termites:** Treatment or corrective action should be recommended if live termites are found. If no evidence of a previous treatment is documented and evidence of infestation is found, even if no live termites are observed, treatment or corrective action by a licensed pest control company should be recommended. Treatment or corrective action may be recommended if evidence of infestation is observed, and a documented treatment occurred previously, unless the structure is under warranty or covered by a service agreement with a licensed pest control company.
For other Wood Destroying Insects, please refer to the NPMA suggested guidelines for added guidance on actions and or treatment.
3. **Obstructions and Inaccessible Areas:** No inspection was made in areas which required the breaking apart or into, dismantling, removal of any object, including but not limited to: moldings, floor coverings, wall coverings, siding, fixed ceilings, insulation, furniture, appliances, and/or personal possessions; nor were areas inspected which were obstructed or inaccessible for physical access on the date of inspection. Your inspector may write out inaccessible areas or use the key in Section IV. Crawl spaces, attics, and/or other areas may be deemed inaccessible if the opening to the area is not large enough to provide physical access for the inspector or if a ladder was required for access. Crawl spaces (or portions thereof) may also be deemed inaccessible if there is less than 24 inches of clearance from the bottom of the floor joists to the surface below. If any area which has been reported as inaccessible is made accessible, the inspection company may be contacted for another inspection. An additional fee may apply.
4. **Consumer Maintenance Advisory Regarding Integrated Pest Management for Prevention of Wood Destroying Insects.** Any structure can be attacked by wood destroying insects. Homeowners should be aware of and try to eliminate conditions which promote insect infestation in and around their structure(s). Factors which may lead to wood destroying insect infestation include: earth to wood contact, foam insulation at foundation in contact with soil, faulty grade, improper drainage, firewood against structure(s), insufficient ventilation, moisture, wood debris in crawlspace, wood mulch or ground cover in contact with the structure, tree branches touching structure(s), landscape timbers and wood decay. Should these or other conditions exist, corrective measures should be taken in order to reduce the chances of infestation of wood destroying insects and the need for treatment.
5. **Neither the inspecting company nor the inspector has had, presently has, or contemplates having any interest in the property inspected.**

AMENDMENT / ADDENDUM TO PURCHASE AGREEMENT



This document forms an integral part of the Purchase Agreement ("Agreement") dated _____, between Diane Nwaonicha ("Buyer") and Jemal O Tamem ("Seller") and Berkshire Hathaway HomeServices RW Towne Realty ("Selling Firm") and AtCoastal Realty ("Listing Firm") for all that certain piece, parcel or lot of land described as follows: 4232 Maplehurst Rd VA 23462 Virginia Beach ("Property").

The undersigned Buyer and Seller hereby agree to the following:

Buyer and Seller agree that Seller shall provide Buyer with a credit in the amount of \$2,000.00 to be applied toward Buyer's closing costs and/or prepaid expenses at settlement. No repairs shall be required of Seller.

Except as expressly set forth above, all of the other terms and conditions of the Agreement not modified above, shall remain unchanged and in full force and effect.

<u>Berkshire Hathaway HomeServices RW Towne Realty</u> (Selling Firm)	(Buyer) <u>Diane Nwaonicha</u> (Date)
By: <u>Bobbi Wood</u> (Date)	(Buyer) _____ (Date)
<u>AtCoastal Realty</u> (Listing Firm)  01/24/2026	 01/24/2026 (Seller) <u>Jemal O Tamem</u> (Date)
By: <u>Shannon Paschall</u> (Date)	(Seller) _____ (Date)

FOR OPTIONAL USE AS PARTIES MAY ELECT