

Reference:

HOME INSPECTION REPORT

Precision Home Inspections, Inc. | CA License #HI-47291

Inspector: Michael Torres | Inspection Date: October 14, 2025 | Report #PHI-2025-1847

Property: 4827 Rolando Blvd, San Diego, CA 92115 | APN: 470-362-18-00

Client: Samantha Chen & David Park | Agent: Kevin Tran, DRE #02134782, Keller Williams

1. STRUCTURAL / FOUNDATION

Type: Raised foundation with concrete perimeter walls and wood-framed floor system. Crawl space accessible.

Condition: Hairline crack observed in south perimeter wall (approximately 3 feet in length, less than 1/16 inch wide). Crack appears consistent with minor cosmetic settling; no displacement or offset noted. **Recommend specialist evaluation** to confirm no structural concern.

Crawl Space: Adequate ventilation. No standing water. Moisture levels within normal range.

2. ROOF

Type: Composition shingle, approximately 15-18 years old.

Condition: Functional but aging. Minor granule loss observed. No active leaks visible from interior. Estimated remaining useful life: 5-8 years. Gutters and downspouts present and functional.

3. ELECTRICAL

Panel: 200-amp main service panel, upgraded per permit (2021). Properly grounded.

Condition: Panel in good condition. GFCI protection present in kitchen, bathrooms, and exterior outlets. No visible hazards.

4. PLUMBING

Supply: Copper supply lines. Good water pressure observed.

Waste: Cast iron waste lines (original). Functional at time of inspection.

Water Heater: 50-gallon gas, approximately 8 years old. Properly strapped. T&P; valve and discharge pipe present.

5. HVAC

Heating: Forced-air gas furnace, original system (~1961). Unit operated at time of inspection.

Cooling: No central air conditioning. Window units noted in two bedrooms.

Condition: Given the age of the furnace (60+ years), replacement should be anticipated. Heat exchanger was not disassembled for inspection — recommend HVAC specialist evaluation. **Estimated replacement cost: \$6,000-\$10,000.**

6. INTERIOR

Floors: Hardwood (refinished). Tile in kitchen and bathrooms.

Walls/Ceilings: Plaster walls in good condition. No visible water stains.

Kitchen: Updated (2019 remodel per seller). Modern appliances.

Bathrooms: Primary bath updated. Secondary bath has original fixtures — functional.

7. EXTERIOR

Siding: Stucco. Minor cracking near foundation (see Section 1).

Windows: Mix of original single-pane and newer dual-pane (replacement). Original windows do not have safety glazing.

Garage: 1-car attached. Automatic opener functional. Fire-rated separation appears intact.

Buyer's Initials (SC)(DP) Seller's Initials (PO)(RO)

4827 Rolando Blvd, San Diego, CA 92115 — Escrow #FNT-2025-09184

8. SUMMARY OF SIGNIFICANT FINDINGS

Item	Severity	Recommendation
Foundation crack (south wall)	Low/Moderate	Specialist evaluation recommended
HVAC system (original 1961)	Moderate	Specialist evaluation; plan for replacement
Termite activity (per seller)	Moderate	Termite (WDO) inspection recommended
Roof aging	Low	Monitor; budget for replacement in 5-8 years

This report is based on a visual, non-invasive inspection performed on the date noted above. Concealed conditions are excluded. This report is not a warranty or guarantee. Client should obtain specialist reports for items flagged above.

Michael Torres

Inspector (Michael Torres)

10/14/2025

Date

Samantha Chen

Client (Samantha Chen)

10/14/2025

Date

Buyer's Initials (SC)(DP) Seller's Initials (PO)(RO)

4827 Rolando Blvd, San Diego, CA 92115 — Escrow #FNT-2025-09184

TRAINING DOCUMENT — SKILLCLOUD ACADEMY. All names, data, and circumstances are fictional. For educational use only.