

MOISTURE INSPECTION REPORT

NAME & ADDRESS OF INSPECTION COMPANY

Eliminator Termite Pest & Moisture Control

ADDRESS OF PROPERTY INSPECTED

4037 Ravine Gap Drive

Suffolk, VA 23434

757-631-2505

Business Lic # 95003779

DATE OF
INSPECTION

2/24/2021

INSPECTION
FEE

90.00

BASED ON A CAREFUL INSPECTION OF THE READILY ACCESSIBLE AREAS OF THE UNDERSTRUCTURE (AS DESCRIBED ON THE REVERSE SIDE) OF THE PROPERTY LISTED ABOVE:

There is evidence of the presence of wood destroying fungi below the floor level of the first main floor.

YES ☐ NO ☒ *HA*

There is evidence of the presence of excessive moisture conditions below the floor level of the first main floor.

(If yes, describe under comments)

YES ☐ NO ☒ *HA*

At the time of our inspection, there were visible damaged wooden members below the floor level of the first main floor caused by fungi.

YES ☐ NO ☒ *HA*

IF ANY DAMAGE IS OBSERVED (AS SHOWN ABOVE) THAT DAMAGE WILL (CHECK ONE BELOW):

☐ Be corrected or has been corrected by this company.

☐ Be corrected by another company, see attached contract.

☐ **NOT** be corrected by this company. This company recommends that damage be evaluated by a qualified building expert and that needed repairs be made.

WERE ANY AREAS OF THE UNDERSTRUCTURE OBSTRUCTED OR INACCESSIBLE?

(If yes, describe under comments)

YES ☐ NO ☒

COMMENTS

Foundation Slab

SIGNATURE OF
INSPECTOR

E. D. J. 50907-C

This report shall not be valid until the following statement of the property owner(s) or their duly authorized representatives is signed:

THE UNDERSIGNED OWNER(S) OF THE ABOVE DESCRIBED INSPECTED PROPERTY HEREBY ACKNOWLEDGE THAT THEY ARE UNAWARE OF ANY PREVIOUS MOISTURE DAMAGE OR DIFFICULTIES INVOLVING MOISTURE THROUGHOUT THEIR OWNERSHIP OF SAID PROPERTY, OTHER THAN AS REPORTED ABOVE.

DATE

PROPERTY
OWNER

PROPERTY
OWNER

ACKNOWLEDGEMENT: Purchaser acknowledges that he has received a copy of this report.

DATE ACKNOWLEDGED

PURCHASER'S SIGNATURE

PLEASE NOTE THE FOLLOWING STATEMENTS:

1. The inspection covered only the readily accessible areas of the understructure including sills, joists, subflooring and substructure support timbers which were visible. It was made only in those areas which were readily accessible and was made in areas where moisture conditions were most likely to occur. No inspection was made in areas which required the breaking apart, dismantling or removal of any object and no inspection was made of any portion of the property other than the foundation and the understructure below the floor level of the first main floor. This report is not a guarantee or warranty as to the absence of moisture condition nor is it a structural integrity report. The Inspector's training and experience do not qualify the inspector in damage evaluation or any other building construction technology and/or repair.
2. If damage from moisture or fungi is discovered, the inspection firm is not responsible to repair any damaged, it is the responsibility of the property owner to determine whether the damage requires repair by having a licensed building contractor or a structural engineer inspect and estimate the necessary repairs, or submit in writing that the damage does not warrant repair.
3. The inspection did not include areas which were obstructed or inaccessible at the time of inspection.
4. This report does not in any way relate to an inspection for infestation or damage from wood destroying insects. Results of any inspection for wood destroying insect infestation or damage is the subject of an entirely separate inspection and report which is in no way involved with the preparation of this report.
5. This report is not a guarantee against future moisture damage or moisture conditions, but is indicative of the conditions of the understructure on the date of inspection. Also wood destroying fungi and/or damaged may exist in visible, concealed or inaccessible areas. The inspection firm cannot guarantee that any moisture condition and/or damaged which may exist as of the date of the inspection. The inspection firm is not responsible for the repair of visible damage which presently exists. It is possible that damaged may presently exist in unexposed or hidden areas of the structure that can't be visually inspected. For this reason the inspection firm cannot guarantee that the damage discovered by a visual inspection of the premises is all the damage which presently exist.
6. This is not a structural damage report. Neither is this a warranty as to the absence of moisture.
7. This report is not a comprehensive moisture report regarding the entire structure but only discloses the results of an inspection of the understructure as described in 1 above. Therefore, this report should not be relied upon in lieu of a physical inspection of the entire premises by any interested parties or persons.