






Generación De Drafmans










Draftman De Fabricación - Ejemplo










Agregar Drill Drawing View










Agregar tabla de perforaciones (Drill table)









Notas de fabricación

- FOR SOLDERMASK TOP USE ARTWORKS NO. 0250-01-ART(2), REVISION A.
- FINISH MUST BE HASL LEAD FREE.
- FOR BOARD CONFIGURATION REFER TO SOLDERMASK BOTTOM USE ARTWORK NO. 0250-01-ART (07)
- PRINT VENDOR INDENTIFICATION AND DATE CODE THIS AREA, IN "SILKSCREEN SECONDARY SIDE" ONLY, SHOULD BE 0.08" FREE OF ANY UNCIVERED COPPER.
- SILKSCREEN: MUST BE WHITE COLOR. SIDE SHOWN USING SHT. 2 TOP LAYER AND SHT. 9 BOTTOM. LAYER, NO SILKSCREEN ON EXPOSED LANDS.
- SOLDERMASK MUST BE BLUE COLOR, LIQUID PHOTOIMAGEABLE (LPI), USE SHT. 3 TOP SIDE AND SHT. 8 BOTTOM SIDE, MAXIMUN CLEARENCE ARROUND LANDS, SMD OR THT AND DRILLS TO BE 0.003".
- ALL HOLES MUST BE PRIMARY DRILLED.
- MAXIMUM ETCH TOLERANCE TO BE +/- 0.002 FOR ALL ARTWORK FEATURES.
- DO NOT PLATE VIA HOLES SHUNT WITH COPPER.
- ANY CHANGE TO STACK-UP NEED TO BE APPROVED BY MiguelR.
- SOME VIAS ARE INTENTIONALLY COVERED BY SOLDERMASK ON BOTTON SIDE
- DIELECTRIC MATERIAL: HIGH TG FR4, TG>175 DEGREES CELSIUS.














Agregar Stack - Up










Agregar las capas del PCB










Draftman De Configuración - Ejemplo










Agregar Drill Drawing View










Agregar cotas










Draftman De Ensamble - Ejemplo









Agregar vistas de ensable

