


Flow Assurance Intelligence Platform (FAIP)

Generated on: 2026-04-05 21:35:35

Executive Summary

Risk Level: HIGH
Maximum Subcooling: 52.11
Minimum Temperature: 9.46 °C

Hydrate Risk Visualization



Detected Flow Assurance Risks

Hydrate Label: Detected
Wax Label: Not Detected
Asphalt Label: Not Detected
Slug Label: Not Detected
Corrosion Label: Not Detected

Engineering Interpretation

Severe hydrate formation risk. High probability of blockage during restart.

Operational Recommendations

- Inject hydrate inhibitors immediately
- Reduce shutdown duration
- Improve insulation
- Use controlled restart procedure