


Flow Assurance Intelligence Report

Risk Level: HIGH
Max Subcooling: 52.11
Minimum Temperature: 9.46 °C



Engineering Interpretation:

Severe hydrate formation risk detected during shutdown conditions.

Operational Recommendations:

- Immediate hydrate inhibitor injection required
- Minimize shutdown duration
- Enhance pipeline insulation
- Controlled restart procedure mandatory