Thomas Schmid


4808 CSE 2260 Hayward Street Ann Arbor, MI 48109-2121 T +1-310-945-6093 thschmid@umich.edu

August 6, 2010


Sunstone Engineering Regarding order X20162793

Dear Sunstone Support,

I received the above mentioned order yesterday. However, the boards have a significant production issue. Please consider the two boards pictured below. The left side is a board we manufactured a month ago (Order X20157444). The right side is the order in question.



As you can see from the highlighted area, the slot on the right hand side is much bigger than the one on the left. While we did increase the slot size by a few mils, we certainly didn't increase it by that much. It also seems that the router had problems creating this slot as the following picture shows.



We were wondering why this mistake happened, as we plan to order several more of these boards. However, with such a bad slot, we won't be able to use them. Please call me at +1-310-945-6093.

Sincerely yours,

Thomas Schmid