Corresponding to REACH stitching wire is a commodity and therefore no safety data sheet is created.

GENERAL INFORMATION

Quick Identification / Company Name:

- Stitching Wire, bright – galvanized – copper coated

- Manufacturer: Dorstener Drahtwerke
  H. W. Brune & Co. GmbH
  Marler Strasse 109
  D - 46282 Dorsten
  phone: +49 (0) 23 62 / 20 99 - 0
  fax: +49 (0) 23 62 / 26 3 95

- Responsible for Preparation: Quality System

SECTION I - IDENTITY

- Common name (used on label): DDD Stitching Wire
- Chemical name: N/A
- Formula: N/A

SECTION II - HAZARDOUS INGREDIENTS

Ingredients		Weight %
Carbon	(C)	≤ 0,10 %
Silicon	(Si)	≤ 0,30 %
Manganese	(Mn)	≤ 0,60 %
Phophorus	(P)	≤ 0,035 %
Sulphur	(S)	≤ 0,035 %
Chromium	(Cr)	≤ 0,20 %
Nickel	(Ni)	≤ 0,25 %
Molybdenum	(Mo)	≤ 0,08 %
Copper	(Cu)	≤ 0,35 %

Steel wires in their usual physical form do not pose any health hazards. However, when subjected to welding, burning, grinding, heat treatment or similar operations, potentially hazardous fumes or dusts, containing extremely low concentrations of manganese, zinc, chromium, ... may be emitted. Non-metallic coatings usually classified as protective coatings or lubricants, may be applied to the surface of steel wire. They are less than 1 % of the weight of the product. Typical coatings are petroleum based oils, phosphates, sodium - or calcium - soap based lubricants, flash or wash metallic coatings of tin and /or copper. The

possible presence of these coatings on steel wire products should be considered during welding or other dust/fume generating activities.

Other hazardous elements such as lead, barium, cadmium are absent or only in a negligible quantity present.

SECTION III - PHYSICAL & CHEMICAL CHARACTERISTICS

Boiling point	N/A
Specific gravity	7,6 - 7,85
Vapor pressure (min. kg)	N/A
Percent volatile by volume	N/A
Vapor density (air)	N/A
Solubility in water	N/A
Reactivity in water	N/A
Appearance and odor	silver gray, odorless

SECTION IV - FIRE & EXPLOSION HAZARD DATA

Flash point	N/A
Flammable limits in air % by volume	
lower	N/A
upper	N/A
extinguisher media	N/A
auto-ignition temperature	N/A
Special fire fighting procedures	Metal fume fever (10g/sq. m iron oxide fumes, 5 mg/sq. m zinc oxide fumes) Do not use water on molten metal. Avoid breathing metal oxide fumes during welding
Unusable fire and explosion hazards	N/A

SECTION V - REACTIVITY DATA

Incompatibility (materials to avoid)	N/A
Hazardous decomposition products	Metal Oxide fumes during burning and welding operations

SECTION VI - HEALTH HAZARDS DATA

Threshold limit value	see section II
Signs and symptoms of exposure	1. Acute overexposure: It is unlikely that overexposure to this material result in acute illness. If symptoms are present, remove from exposure and consult a physician. 2. Chronic overexposure:
Medical conditions generally	

aggravate by exposure	N/A
Chemical listed as carcinogen or potential carcinogen	N/A
National toxicology program	N/A
I.A.R.C. monographs	N/A
OSHA regulated?	N/A
OSHA permissible exposure limit	Iron oxide fumes (Fe2O3):10 mg/sq. m
ACGIH limit value	Zink oxide fumes (ZnO):5 mg/sq. m
Other exposure limit used	N/A
Emergency and first aid procedures	N/A
1. Inhalation	Remove form excessive exposure levels unless proper respiratory protection is worn.
2. Eyes	Immediately flash with water, get medical attention.
3. Skin	If irritation develops, remove clothing and wash well with soap and water.
4. Ingestion	N/A

SECTION VII - SPECIAL PROTECTION INFORMATION

Respiratory protection (specify type)	Operations such as welding, burning, sawing, should be performed in a ventilated area. Avoid breathing metal oxide fumes during welding.
Ventilation	N/A
Local exhaust	N/A
Mechanical (general)	N/A
Special	N/A
Other	N/A
Protective gloves	When cutting wires.
Eye protection	Necessary during handling.
Other protective clothing or equipment	N/A
Work/hygienic/practices	Arc or spark generated when welding could be a source of ignition for combustible or flammable products.

SECTION VIII - SPECIAL PRECAUTIONS AND SPILL / LEAK PROCEDURES

Precautions to be taken in handling storage	Eye protection and protective gloves. When handling, there is a risk of laceration from sharp cut ends. Care should be taken when removing ties from coils or bundles which may spring open.
Other precautions	N/A
Steps to be taken in case material being released or spilled	Remove spilled wire to prevent slipping and stumbling hazard.
Waste disposal methods	Excess product can be recycled or disposed in accordance with local regulations.

N/A = not applicable