Top 15 Feature Importances (Random Forest)

Feature	Importance
gx_mean	0.0150
gx_max	0.0147
ax_kurtosis	0.0141
gx_energy	0.0138
gx_min	0.0123
ax_abs_energy	0.0120
gx_std	0.0118
highx_range	0.0114
gx_range	0.0112
highx_std	0.0108
highx_kurtosis	0.0108
highx_min	0.0107
ax_skew	0.0105
highy_max	0.0105
ax_energy	0.0102

Importance