
EK | Team 103 | JLCDFM Results

Uploaded EK103.zip | 2 copper layers | 80 x 65 mm | 20 October 2026



0 danger findings

7 warnings

All seven warnings:
Unconnected trace end
Top.art

The site listed each object as r39.3701. This corresponds to a 1.0 mm stroke.

The Gerber contains seven 1.0 mm line segments forming the required EK copper lettering. This is a likely explanation, not a location-verified dismissal.

Actual JLCDFM screenshot, unchanged. Analysis completed and results persisted after reload. The geometric viewer remained on "Retrieving DFM data" and the site PDF export stalled, so detailed location confirmation and a native JLCDFM PDF could not be obtained. This document captures the observed results and does not claim a warning-free pass.

JLCDFM PCB analysis - observed category totals

Counts are Danger, Warning, Good. Captured from the rendered JLCDFM results.

- Sharp trace corner 0, 0, 0
- BGA pad 0, 0, 0
- Via placed within a pad 0, 0, 0
- Trace to board edge 0, 0, 0
- Trace spacing 0, 0, 0
- Unconnected trace end 0, 7, 0
- Trace width 0, 0, 0
- Fiducial 0, 0, 0
- Pad to board edge 0, 0, 0
- Pad spacing 0, 0, 0
- Plated through-hole to trace clearance 0, 0, 0
- Annular ring 0, 0, 0
- tht to smd 0, 0, 0
- Via to pad 0, 0, 0
- Soldermask bridge 0, 0, 0
- Solder mask opening exposing trace 0, 0, 0
- Soldermask opening with multiple segments 0, 0, 0
- Negative soldermask expansion 0, 0, 0
- Silkscreen to pad 0, 0, 0
- Silkscreen to hole 0, 0, 0
- Silkscreen line width 0, 0, 0
- Unconnected via 0, 0, 0
- Missing plated through-hole 0, 0, 0
- Unconnected via 0, 0, 0
- Plated through-hole spacing 0, 0, 0
- Short slot detection 0, 0, 0
- Slot width check 0, 0, 0
- Via to PTH spacing 0, 0, 0
- Unconnected via 0, 0, 0

Result: https://jlcdfm.com/viewer?pcbUploadFileId=635369139561779202