

1. Overview & specifications

The AuraClean Air Purifier AC-500 (AuraClean, air-purifier) is covered by this service manual for authorised technicians holding the 'general-hvac' skill. It documents diagnosis, fault codes, and board/mechanical-level repair.

Specifications — type: HEPA air purifier, cadr: 400, powerW: 55.

Warranty: 12 months. Parts and labour on the motor and PCB 12 months. HEPA and carbon filters are consumables.

Reference: <https://support.example-fieldflow.test/ac-500/manual>

AuraClean Air Purifier AC-500 — Service Manual — page 1

2. Installation & commissioning

Remove the filter wrapping, seat the HEPA and carbon stacks, and calibrate the PM sensor in clean air for two minutes.

Record the serial number and commissioning date against the work order. A failed self-test must be cleared before the visit is closed.

3. Fault codes

A1 — Fan not spinning; blower motor fault. Replace MOT-500. Skill: general-hvac.

A3 — Air-quality always red; PM sensor drift. Replace PM-500. Skill: general-hvac.

A5 — Filter-life alert (consumable, no covered part). No part required; inspect and reset. Skill: general-hvac.

4. Part replacement — MOT-500 / PCB-500

MOT-500 — Brushless blower motor (motor). Isolate mains and follow the safety SOP. Remove the faulty unit, fit MOT-500, and run the self-test. Requires 'general-hvac'. This part is covered under active warranty (free). List price ■1,650.

PCB-500 — Air-quality control board (board). Isolate mains and follow the safety SOP. Remove the faulty unit, fit PCB-500, and run the self-test. Requires 'general-hvac'. This part is covered under active warranty (free). List price ■1,100.

5. Part replacement — PM-500 / HEPA-500

PM-500 — Laser PM2.5 sensor (sensor). Isolate mains and follow the safety SOP. Remove the faulty unit, fit PM-500, and run the self-test. Requires 'general-hvac'. This part is covered under active warranty (free). List price ■720.

HEPA-500 — True-HEPA filter (consumable). Isolate mains and follow the safety SOP. Remove the faulty unit, fit HEPA-500, and run the self-test. Requires 'general-hvac'. This part is chargeable (out of warranty scope). List price ■900.

6. Part replacement — CARB-500

CARB-500 — Activated carbon filter (consumable). Isolate mains and follow the safety SOP. Remove the faulty unit, fit CARB-500, and run the self-test. Requires 'general-hvac'. This part is chargeable (out of warranty scope). List price ■550.

7. Maintenance, safety & warranty

Maintenance: inspect at each visit; clean or replace consumables on the service interval; log any recurring fault code.

Isolate mains; the motor capacitor can hold charge.

Warranty annex: under an active warranty, MOT-500, PCB-500, PM-500 are replaced free with labour. Consumables and cosmetic parts are never covered. If warranty is expired or the fault is outside the original scope, the part is chargeable: a quote is raised and payment is collected before the visit is confirmed.

Policy reference: <https://support.example-fieldflow.test/warranty/v5>