

1. Overview & specifications

The Glacio Double-Door Refrigerator DD-410 (Glacio, refrigerator) is covered by this service manual for authorised technicians holding the 'refrigeration' skill. It documents diagnosis, fault codes, and board/mechanical-level repair.

Specifications — type: frost-free double door, capacityL: 410, refrigerant: R600a, starRating: 3.

Warranty: 120 months. Compressor covered 10 years; other parts and labour 12 months. Door gaskets and trays are consumables.

Reference: <https://support.example-fieldflow.test/dd-410/manual>

Glacio Double-Door Refrigerator DD-410 — Service Manual — page 1

2. Installation & commissioning

Let the unit stand upright for four hours before power-on, level the cabinet, and confirm the door gasket seals a paper strip on all four sides.

Record the serial number and commissioning date against the work order. A failed self-test must be cleared before the visit is closed.

3. Fault codes

C1 — No cooling; compressor not starting. Replace COMP-410. Skill: refrigeration.

C2 — Fridge control board failure. Replace PCB-410. Skill: refrigeration.

C5 — Heavy frost build-up; defrost heater open. Replace DEFR-410. Skill: refrigeration.

C7 — Warm fridge, cold freezer; evaporator fan stalled. Replace FANE-410. Skill: refrigeration.

C9 — Door-open alarm; gasket leak (consumable). No part required; inspect and reset. Skill: refrigeration.

4. Part replacement — COMP-410 / PCB-410

COMP-410 — Hermetic compressor R600a (compressor). Isolate mains and follow the safety SOP. Remove the faulty unit, fit COMP-410, and run the self-test. Requires 'refrigeration'. This part is covered under active warranty (free). List price ■12,500.

PCB-410 — Inverter fridge control board (board). Isolate mains and follow the safety SOP. Remove the faulty unit, fit PCB-410, and run the self-test. Requires 'refrigeration'. This part is covered under active warranty (free). List price ■3,200.

5. Part replacement — FANE-410 / DEFR-410

FANE-410 — Evaporator fan motor (motor). Isolate mains and follow the safety SOP. Remove the faulty unit, fit FANE-410, and run the self-test. Requires 'refrigeration'. This part is chargeable (out of warranty scope). List price ■1,450.

DEFR-410 — Defrost heater element (heating-element). Isolate mains and follow the safety SOP. Remove the faulty unit, fit DEFR-410, and run the self-test. Requires 'refrigeration'. This part is chargeable (out of warranty scope). List price ■880.

6. Part replacement — THRM-410 / GASK-410

THRM-410 — Defrost thermostat (thermostat). Isolate mains and follow the safety SOP. Remove the faulty unit, fit THRM-410, and run the self-test. Requires 'refrigeration'. This part is chargeable (out of warranty scope). List price ■420.

GASK-410 — Door gasket set (consumable). Isolate mains and follow the safety SOP. Remove the faulty unit, fit GASK-410, and run the self-test. Requires 'refrigeration'. This part is chargeable (out of warranty scope). List price ■600.

7. Part replacement — SENS-410

SENS-410 — Evaporator temperature sensor (sensor). Isolate mains and follow the safety SOP. Remove the faulty unit, fit SENS-410, and run the self-test. Requires 'refrigeration'. This part is covered under active warranty (free). List price ■380.

8. Maintenance, safety & warranty

Maintenance: inspect at each visit; clean or replace consumables on the service interval; log any recurring fault code.

R600a is flammable: no open flame, ensure ventilation, and recover before brazing.

Warranty annex: under an active warranty, COMP-410, PCB-410, SENS-410 are replaced free with labour. Consumables and cosmetic parts are never covered. If warranty is expired or the fault is outside the original scope, the part is chargeable: a quote is raised and payment is collected before the visit is confirmed.

Policy reference: <https://support.example-fieldflow.test/warranty/v5>

Glacio Double-Door Refrigerator DD-410 — Service Manual — page 8