

1. Overview & specifications

The HeatWave Convection Microwave MW-28 (HeatWave, microwave) is covered by this service manual for authorised technicians holding the 'kitchen-appliance' skill. It documents diagnosis, fault codes, and board/mechanical-level repair.

Specifications — type: convection microwave, capacityL: 28, powerW: 900.

Warranty: 36 months. Magnetron covered 36 months; other parts and labour 12 months.

Reference: <https://support.example-fieldflow.test/mw-28/manual>

HeatWave Convection Microwave MW-28 — Service Manual — page 1

2. Installation & commissioning

Confirm the cavity is clear, verify the door interlocks cut power when opened, and run a one-minute water-load heat test.

Record the serial number and commissioning date against the work order. A failed self-test must be cleared before the visit is closed.

3. Fault codes

M1 — No heating in microwave mode; magnetron failed. Replace MAG-28. Skill: kitchen-appliance.
SAFETY: high-risk, follow discharge/isolation SOP.

M2 — Sparking / HV fault; transformer breakdown. Replace HVT-28. Skill: kitchen-appliance.
SAFETY: high-risk, follow discharge/isolation SOP.

M4 — No convection heat; element open. Replace HEAT-28. Skill: kitchen-appliance.

M6 — Won't start; door interlock not engaging. Replace DOOR-28. Skill: kitchen-appliance.
SAFETY: high-risk, follow discharge/isolation SOP.

4. Part replacement — MAG-28 / HVT-28

MAG-28 — Magnetron tube (mechanical). Isolate mains and follow the safety SOP. Remove the faulty unit, fit MAG-28, and run the self-test. Requires 'kitchen-appliance'. This part is covered under active warranty (free). List price ■2,100.

HVT-28 — High-voltage transformer (board). Isolate mains and follow the safety SOP. Remove the faulty unit, fit HVT-28, and run the self-test. Requires 'kitchen-appliance'. This part is covered under active warranty (free). List price ■1,750.

5. Part replacement — PCB-28 / DOOR-28

PCB-28 — Touch control board (board). Isolate mains and follow the safety SOP. Remove the faulty unit, fit PCB-28, and run the self-test. Requires 'kitchen-appliance'. This part is chargeable (out of warranty scope). List price ■1,300.

DOOR-28 — Door interlock switch set (mechanical). Isolate mains and follow the safety SOP. Remove the faulty unit, fit DOOR-28, and run the self-test. Requires 'kitchen-appliance'. This part is chargeable (out of warranty scope). List price ■580.

6. Part replacement — FANC-28 / HEAT-28

FANC-28 — Convection fan motor (motor). Isolate mains and follow the safety SOP. Remove the faulty unit, fit FANC-28, and run the self-test. Requires 'kitchen-appliance'. This part is chargeable (out of warranty scope). List price ■960.

HEAT-28 — Convection heating element (heating-element). Isolate mains and follow the safety SOP. Remove the faulty unit, fit HEAT-28, and run the self-test. Requires 'kitchen-appliance'. This part is chargeable (out of warranty scope). List price ■840.

7. Maintenance, safety & warranty

Maintenance: inspect at each visit; clean or replace consumables on the service interval; log any recurring fault code.

Discharge the HV capacitor to chassis before any work. The magnetron carries lethal voltage even unplugged.

Warranty annex: under an active warranty, MAG-28, HVT-28 are replaced free with labour. Consumables and cosmetic parts are never covered. If warranty is expired or the fault is outside the original scope, the part is chargeable: a quote is raised and payment is collected before the visit is confirmed.

Policy reference: <https://support.example-fieldflow.test/warranty/v5>