
All process signals (actuators → sensors)
sliderMagazine
motorTurntable
drillActive
weldActive
rotateToConveyor
vacuumGripper
conveyorBelt
separatorValve
sliderMotor
rotateToTable (rep)
turntableInPosition (sensor)
magazineEmpty (sensor)
workpieceOnConveyor (sensor)
workpieceOnPallet (sensor)
sliderInPosition (sensor)
transferUnitAtTurntable (sensor)
transferUnitAtConveyor (sensor)
0
50
100
150
200
250
300
time (s) — averaged over kept trials, laid end-to-end