

(h) Quality Assurance

Students should be taught to:

plot sample means, median and ranges over time.

To view consistency and accuracy against a target value in cases where a process is off-target. For example, in the manufacture of clothes to test that the variation in waist size is within the allowable limits of production and may continue; in the manufacture of engineering components that certain measurements are within allowable limits.