

5.5 Stock forms, types and sizes in order to calculate and determine the quantity of components required	To apply knowledge and understanding of the advantages, disadvantages and applications of the following stock forms/sizes, in order to be able to discriminate between them and select and apply appropriately.
	5.5.1 Stock forms/types: - a tolerances, ratings and values – such as E12 series resistors - b surface-mount technology (SMT) - c through-hole components.
	5.5.2 Sizes: - a unit of current (amp) - b unit of resistance (ohm) - c unit of potential difference (volt) - d applications of Ohm's Law: $V = I \times R$ - e resistors in series: $R_{\text{total}} = R_1 + R_2 + R_3$ etc. - f resistors in parallel: $1/R_{\text{total}} = 1/R_1 + 1/R_2 + 1/R_3$ etc. - g área - h diameter.