

Black Rock Motorworks Ltd

15 Uxbridge Road
Hayes
London
UB4 0JN
07577451045
Block Rock Motorworks

ESTIMATE INVOICE ONLY

KW201390

DATE

26/08/2026

TOTAL

GBP £80.00

TO

NAFEESA HUSSAIN

REG: LX19 NAE

MAKE: LAND ROVER- RANGE ROVER

MODEL: VOUGE

DESCRIPTION	AMOUNT
***** DIAGNOSTICS REPORT ********	£80.00

1. Diagnostic inspection carried out

A diagnostic scan has been carried out on the above vehicle using professional diagnostic equipment. The scan identified the following confirmed diagnostic trouble codes (DTCs) across multiple vehicle control modules.

2. Engine control module (ECM)

The following faults were recorded:

- P0234-77 – Turbocharger/supercharger overboost condition; commanded position not reachable.
- P250B-29 – Engine oil level sensor circuit fault (additional description requires confirmation).
- P250D-37 – Engine oil level sensor circuit high; signal frequency too high.
- P250C-36 – Engine oil level sensor circuit fault; signal frequency too high.
- P250A-38 – Engine oil level sensor circuit fault; signal frequency incorrect.
- P250B-87 – Engine oil level sensor communication/message fault.
- P0196-29 – Engine oil temperature sensor circuit range/performance; signal invalid.
- U0402-00 – Invalid data received from the transmission control module (additional sub-type not visible).

3. Other control module faults

Thanks for your business!

- U2300-54 – Central configuration: missing calibration.
- U0001-82 – High-speed CAN communication bus fault; alive/sequence counter incorrect or not updated.
- B1DE3-31 – Multimedia link/driver assistance domain controller: no signal.
- B1B33-81 – Target identification transfer: invalid serial data received.
- B1412-87 – Gateway module: quiescent relay box missing message.
- U0080-87 – Transfer case control module: vehicle communication bus F, missing message.
- U0100-87 – Lost communication with engine control module; missing message.
- U0115-87 – Lost communication with engine control module; missing message.
- U101C-87 – Lost communication with PCM node; missing message.
- U101D-87 – Lost communication with PCM node; missing message.
- U101E-87 – Lost communication with PCM node; missing message.
- U0056-87 – Vehicle communication bus D: missing message.
- B14A9-13 – Telematics communication link: open circuit.
- B14AA-13 – Telematics communication link: open circuit.
- P2101-84 – Throttle actuator control motor circuit range/performance fault (description should be verified against the full diagnostic record).
- U0042-00 – Invalid data received; complete source module and sub-type require confirmation.

4. Diagnostic findings and conclusion

The diagnostic scan has identified multiple confirmed faults relating to engine boost control, engine oil level and temperature sensor signals, vehicle network communications, control module messaging, configuration/calibration and telematics connectivity.

The above codes represent the results recorded by the diagnostic equipment at the time of inspection. Further testing may be required to establish the underlying cause of each fault and determine whether individual components, wiring, connections, power supplies or control module configuration are responsible.

TOTAL	GBP £80.00

ESTIMATOR'S COMMENTS

This estimate has been prepared following a visual inspection of the vehicle and is subject to hidden or supplementary damage being identified once dismantling has commenced. Any additional repairs required will be notified before work proceeds.

All replacement components will be supplied to manufacturer specification unless otherwise agreed. Paintwork will be colour matched using professional refinishing systems to achieve the highest possible

finish.

Estimated Repair Time: Approximately 5 working days, subject to parts availability.