EC4.404: Mechatronics System Design

Harikumar Kandath

Robotic Research Center, IIIT Hyderabad

harikumar.k@iiit.ac.in

Lecture 6, Feb 18, 2025

General Information

Mechatronics: Study of the integration of mechanical hardware, electrical/electronic hardware with computer hardware and software. Named by Tetsuro Mori from Japan when working with Yaskawa Electric Coorporation. Applications: Robotics, Aerospace industry, automotive industry, process industry etc.

Course Objective: To introduce the design and development of a mechatronic system.

Instructors: Harikumar Kandath and Nagamanikandan Govindan.

Sensors in Ground Robot

- Wheel Encoder
- Magnetometer
- Inertial Measurement Unit (IMU): contains Accelerometer and Gyroscope.
- Global Positioning System (GPS)
- Range measuring sensor (LIDAR, ultrasonic, camera)

Sensors in UAV

- Inertial Measurement Unit (IMU) contains Accelerometer and Gyroscope.
- Altimeter
- Airspeed sensor
- Magnetometer
- Global Positioning System (GPS)
- Range measuring sensor (LIDAR, ultrasonic, RADAR, camera)

Sensors in Robotic Manipulator

- IMU
- Encoder
- Force-Torque sensor
- Camera

Force-Torque Sensor

Force sensors are designed to detect forces applied between their base and sensing plate. Force-Torque Sensors, also known as FT Sensors, detect both forces and torques. They are usually placed on a robot's arm, just before the end-effector.



Figure: Force-Torque sensor installed in a robotic manipulator

Force-Torque Sensor

- Piezoelectric
- Strain Gauge
- Capacitive




Figure: Strain Gauge

Strain Gauge: Basics

strain = δ_d/d (change in dimension/ original dimension).

$$E = \frac{stress}{strain} \tag{1}$$

E is the Young's modulus of the material.

$$e_T = -\nu e_L \tag{2}$$

 e_T is the transverse strain and e_L is the longitudinal strain and ν is the Poisson ratio (0.25 to 0.40).

$$R = \frac{\rho I}{A} \tag{3}$$

R is the resistance in ohms, I is the length of the material, A is the cross sectional area and ρ is the resistivity in ohm-m.

Relation between applied force and change in resistance

NB: Applied force is called "stress" here.

$$\frac{\Delta R}{R} = \frac{\Delta I}{I} - \frac{\Delta A}{A} + \frac{\Delta \rho}{\rho} \tag{4}$$

$$\frac{\Delta R}{R} = (1 + 2\nu)e_L + \frac{\Delta \rho}{\rho} \tag{5}$$

$$\frac{\Delta R}{R} = Ge_L \tag{6}$$

$$G = (1 + 2\nu) + \frac{1}{e_L} \frac{\Delta \rho}{\rho} \tag{7}$$

G is the gauge factor (2.0 to 2.2).

Actuators

Role of Actuator: To enable/disable or to control motion.

- Motor: DC motor, Servo motor, Stepper motor, BLDC motor.
- Control valve: ON-OFF (solenoid), linear, quick opening, equal percentage.

Key parameters:

- Amplitude range
- Bandwidth
- Slew rate
- Power output
- Efficiency



Direct Current (DC) Motor




Figure: Parts of a DC motor

DC Motor - Basic Equations

Motor torque τ_m (Nm), current i_m (A), K_t is the torque constant (Nm/A), η_m is the motor efficiency (0-1), $\omega_m = \frac{d\theta_m}{dt}$ is the motor angular velocity (rad/s).

$$\tau_m = K_t i_m \tag{8}$$

Power input (w)

$$P_{in} = V_m i_m \tag{9}$$

Power output (w)

$$P_{out} = \tau_m \omega_m \tag{10}$$

Considering losses,

$$P_{out} = \eta_m P_{in} \tag{11}$$

$$\tau_m \, \omega_m = \eta_m V_m i_m \tag{12}$$

$$\omega_m = \frac{\eta_m}{K_t} V_m \tag{13}$$

Dynamics

Electrical circuit

$$L\frac{di_m}{dt} + Ri_m + E_b = V_m \tag{14}$$

Mechanical circuit

$$J\frac{d^2\theta_m}{dt^2} + B\frac{d\theta_m}{dt} + k\theta_m = \tau_m - \tau_I \tag{15}$$

Back EMF

$$E_b = K_m \omega_m \tag{16}$$

DC Servomotor

DC Servomotor: A DC motor with angular position feedback and control mechanism to maintain the desired angular position under varying load torque.




Figure: Servomotor: DC motor with encoder feedback

Brush-Less Direct Current (BLDC) Motor




Figure: Brush-Less DC motor with 3 phases

Input to (BLDC) Motor




Figure: Input sequence to Brush-Less DC motor

Stepper Motor

Rotates for a specified angular displacement and then stop.




Figure: Stepper motor: Winding arrangement for 30° rotation.

Control Valves

Control valves regulate the flow of a fluid (liquid or gas).

- ON-OFF (Solenoid) valve.
- Quick opening valve.
- Linear valve.
- Equal percentage valve.

Basic operation

Pneumatic signal based control.

Change in flow rate related to change in pressure across the valve opening.




Figure: Working of a control valve valve valve

Types of Valve

I: Linear, II: Equal percentage, III: Quick opening.




Figure: Input-Output relation for 3 types of control valves

THANK YOU

21 / 21