

Vessel Inspection Report

Table of Contents

- 1. Executive Summary
- 2. Vessel Repair Summary
- 3. Defect Analysis
 - 3.1 PD_1
 - 3.2 PD_2
 - 3.3 PD_3
 - 3.4 PD_4

1. Executive Summary

Generation failed.

2. Vessel Repair Summary

Metric	Value
Total Defects	4
Total Estimated Cost	221778.82 INR
Material Cost	133067.29 INR
Labor Cost	66533.65 INR
Equipment Cost	22177.88 INR

3. Defect Analysis

3.1 PD_1

Defect Overview

Generation failed.

Visual Evidence



Repair Procedure

Generation failed.

Repair Cost Breakdown

Item	Quantity	Unit Cost	Total Cost	Currency
Cutting Torch (rental)	0.08	10764.0	807.3	INR

Estimated Repair Cost: 41583.53 INR

3.2 PD_2

Defect Overview

Generation failed.

Visual Evidence



Repair Procedure

Generation failed.

Repair Cost Breakdown

Item	Quantity	Unit Cost	Total Cost	Currency
Cutting Torch (rental)	0.08	10764.0	807.3	INR

Estimated Repair Cost: 41583.53 INR

3.3 PD_3

Defect Overview

Generation failed.

Visual Evidence



Repair Procedure

Generation failed.

Repair Cost Breakdown

Item	Quantity	Unit Cost	Total Cost	Currency
Cutting Torch (rental)	0.12	10764.0	1345.5	INR

Estimated Repair Cost: 69305.88 INR

3.4 PD_4

Defect Overview

Generation failed.

Visual Evidence



Repair Procedure

Generation failed.

Repair Cost Breakdown

Item	Quantity	Unit Cost	Total Cost	Currency
Cutting Torch (rental)	0.12	10764.0	1345.5	INR

Estimated Repair Cost: 69305.88 INR