UGANDA MARTYRS UNIVERSITY

NKOZI

UNIVERSITY EXAMINATIONS

FACULTY OF SCIENCE

DEPARTMENT OF MATHEMATICS & STATISTICS

December, 2022

STA 2102: STATISTICAL QUALITY CONTROL

Bsc.Gen. (II)

DATE: Thursday, 15/12/2022

DURATION: 3HRS (2:00 - 5:00 PM)

VENUE:

Instructions:

- 1. Carefully read through ALL the questions before attempting
- 2. ANSWER any four Questions.
- 3. Provide all the outputs for all procedures
- 4. Ensure your work is clear and readable. Untidy work shall be penalized
- 5. Any type of examination Malpractice will lead to automatic disqualification
- 6. Do not write anything on the questions paper.

QUESTION ONE

- (a) Define statistical quality control (SQC) [1 Mark]
 - (b) State the causes of variations in any process [4 marks]
 - © Consider the data below as collected from the industries

		RE	ADIN	IGS	
		1	2	3	4
	9:00 am	40	50	55	39
	9:30 am	44	42	38	38
TIME	10:00 am	41	45	47	43
	10:30 am	39	39	41	41
	11:00 am	37	42	46	41
	11:30 am	39	40	39	40

- (i) Design a mean chart and interpret it. [10 marks]
- (ii) On the same diagram, design the range chart and interpret it. [10 marks]

QUESTION TWO

(a) List and explain different control charts that are commonly used in different processes.

[10 marks]

(b) A random sample of 100 ball pens was taken from a firm which produces pens and a number of defective pens were noted. This was repeated for 10 times as shown below. Using the information given prepare a 'P' control chart and comment on the results. [15 marks]

Sample	1	2	3	4	5	6	7	8	9	10
	_									

No. of defectives	To	-	-	-							
No. of defectives	8	11	13	8	17	7	7	14	6	9	1
											1

QUESTION THREE

An automatic machine produces 5.0 millimeter bolts at a high rate of speed. A quality-control program has been started to control the number of defectives.

The quality-control inspector selects 50 bolts at random and determines how many defectives are. The numbers defectives for the first 10 samples follow.

Sample number	1	2	3	4	5	6	7	8	9	10
Size of the sample	50	50	50	50	50	50	50	50	50	50
Number of defectives	3	5	0	4	1	2	6	5	7	7

- (a) Design a percent defective chart [10 marks]
- (b) Plot the number of defects for the first 10 samples on the chart. [10 marks]
- (c) Interpret the chart. [5 marks]

QUESTION FOUR

- (a) Define the following terms as applied to SQC
 - (i) process capability
 - (ii) process capability ratio [2 marks@]
- (b) In a sample of 10 units, the lower and upper specification limits were given as 1 and 2 respectively. If the average range in the experiment is 0.325. Estimate the process capability of the machine (d2 = 3.078). [8 marks]
- © consider the table of sample observations

Sample number	X ₁	X ₂	X ₃
1	6.0	5.8	6.1
2	5.2	6.4	6.9
3	5.5	5.8	5.2

4	5.0	5.7	6.5
5	6.7	6.5	5.5
6	5.8	5.2	5.0
7	5.6	5.1	5.2
8	6.0	5.8	6.0
9	5.5	4.9	5.7
10	4.3	6.4	6.3
11	6.2	6.9	5.0
12	6.7	7.1	6.2

(i) Plot the sample standard deviations against the sample numbers [10 marks]

(ii) Draw the s-chart and comment on the results. [5 marks]

QUESTION FIVE

- (a) Define the following terms as applied to SQC
 - (i) OC curve
 - (ii) Producers risk
 - (iii) Consumers risk
 - (iv) Acceptance sampling [2.5 marks @]

(b)A firm purchases diskettes from diskettes international. The diskettes are packed in lots of 1000 each. The manager has agreed to accept lots with 10% or fewer defective diskettes. He has directed his inspection department to select a sample of 20 diskettes and examine them carefully. He will accept the lot if it has 2 or fewer defectives in the sample. Develop an OC curve for this inspection plan. What is the probability of accepting a lot that is 10% defective? [15 marks]

QUESTION SIX

- (a) What is the regression analysis? [1 mark]
- (b) Write down the least squares equations for estimating the regression constants

[4 marks]

© A machine hire company kept records of the age X (years) and the maintenance costs \$ Y of one type of machine. The following table summarizes the data for a random sample of 10 of the machines.

Age (X) years	63	12	34	81	51	14	45	74	24	89
Cost \$(Y)	111	25	41	181	64	21	51	145	43	241

- (i) Fit an equation of the least squares of Y on X [5 Marks]
- (ii) Determine the cost of maintenance of a 35 year old machine.[4 marks]
- (iii) Calculate the product moment correlation coefficient between X and Y [5 marks]
- (iv) Determine coefficient of determination [3 Marks]
 - (v) Interpret your answers from (ii) and (iii). [3 marks]

END