LOAD CELL INPUT READING SHOULD B E Z E R O (DELAY=500ms)

AFTER INSERTING
ROCKET MOTOR
CALIBRATE IT TO
ZERO(DELAY =
500ms)

BLUETOOTH RECEIVER IGNITOR-CHECK IGNITOR ON/ OFF(DELAY = 500ms)

IF ON THEN SWITCH ON RELAY FOR ONLY 1 SECOND (WHICH IS

S T A R T RECORDING READINGS AND CONVERT IT INTO CSV 1 COLUMN FOR TIMESTAMP AND 2nd FOR GRAM WEIGHT (MOTOR IS STARTED) (DELAY = 1ms)

TURN OFF AFTER RECEIVING TURN OFF BUTTON SIGNAL FROM BLUETOOTH(DELA Y = 1ms)

EMERGENCY TURN OFF EVERYTHING (DELAY = 1ms)