OPERATIONS

Internal Use Only

Equipment Performance Factor

Measure and track the actual performance of individual equipment against its designed output rate to identify and



WHEN TO USE

When machine output is inconsistent or below standard; before a capital investment decision on replacement or upgrade.

HOW TO APPLY — STEPS

1. Define the rated (nameplate) capacity for the machine under normal conditions
2. Measure actual output over at least two representative production weeks
3. Calculate performance factor = actual output / rated output x 100%
4. Investigate root causes of the performance gap by shift and product
5. Implement and verify improvement actions systematically

PRACTITIONER TIP

! Measure over at least two full weeks to capture shift-to-shift variation and recurring faults across the full cycle.

KEY OUTPUTS

- Performance factor trend chart by machine
- Loss analysis by category
- Targeted improvement action plan

HOW TO MEASURE SUCCESS

Performance factor % increase; variability reduction between shifts; comparison to rated specification

TOOL CATEGORY
Operations