CompanySync

DRONE DAMAGE INSPECTION REPORT

216-777-7154 • io.companysync@gmail.com

675 Alpha Dr , Highland Hts, OH 44143

John

DRONE-89757012

Property Information

Customer: John

Address: 13901 Southview

Inspection Date: 2026-02-11

Weather: clear

Executive Summary

Overall Condition	Hail Detected	Wind Detected
POOR	**NO**	**NO**

Damage Assessment & Recommendation

Recommendation: FULL REPLACEMENT

FULL REPLACEMENT (Due to Material Discontinuation & Matching Code)

Justification:
Minimal impact to the overall water-shedding capabilities and structural integrity.

CRITICAL MATCHING ISSUE (OAC 3901-1-54): An ITEL report confirmed that the existing roofing material is discontinued/unavailable.

Pursuant to Ohio Administrative Code (OAC) 3901-1-54 (H)(1)(b), "When an interior or exterior loss requires replacement of an item and the replaced item does not match the quality, color or size of the item suffering the loss, the insurer shall replace as much of the item as to result in a reasonably uniform appearance."

Since a reasonably uniform appearance cannot be achieved through spot repairs, replacement of the affected slopes/elevations is required to restore the property to its pre-loss condition.

Overall Summary

Visual Evidence

Analysis completed

Severity: MINOR

& Likely Discontinued

Severity: MODERATE

The roof is generally intact but exhibits considerable signs of aging and potential damage. Some shingles are curling and have lost granules, indicating degradation over time, which may lead to leaks or further deterioration if not addressed promptly.

Photo 3

Section: General

Severity: MODERATE

The roof has significant visible damage, including cracked shingles and areas of missing granules. This indicates a moderate level of deterioration, but overall, portions of the roof remain intact.

Analysis completed

Severity: MODERATE

Analysis completed

Photo 5

Section: General

Severity: MODERATE

The roof is in moderate condition with visible damage including missing shingles, curling, and significant granule loss. The overall integrity of the roof appears compromised but not completely intact.

Photo 7

Section: General

The roof appears intact with no major visible damage. The shingles have some wear but remain overall functional. No missing or significantly damaged sections are noted.

Analysis completed

Photo 9

Section: General

The roof appears to be intact with no visible major damage. The shingles are slightly worn, but there are no significant issues noted that would compromise the integrity of the roof.

& Likely Discontinued

Severity: MODERATE

The roof shows signs of moderate deterioration with visible areas of missing shingles and significant granule loss, indicating an overall compromised condition. While the roof structure appears intact, these issues may lead to further damage if not addressed.

Photo 11

Section: General

Severity: MINOR

Analysis completed



Severity: MODERATE

The roof appears to have some surface wear, with visible granule loss and debris accumulation. There are no major missing shingles or significant structural damage. Overall, while the roof is intact, its condition indicates moderate wear and may need attention to prevent further deterioration.

Photo 13

Section: General

Severity: SEVERE

Analysis completed

The roof surface is largely intact, showing a consistent color and texture without significant defects.

Photo 15

Section: General

Analysis completed