



General Details

Assessor	Samuel Prieto Ayllon
Assessment Date	02/07/2025
Assigned Reviewer	Samuel Prieto Ayllon
Next Review Date	02/07/2026

Signed Off By	Oraib AlKheetanRojas
Signed Off On	19/05/2026
Sign Off Comments	

Operation Assessed	Motion capture system Vicon Vantage operation
--------------------	---

Associated with specific area

 Basement 2

 B2 029 (Robotics Lab)

 CTP

Description of work area and/or activity assessed

Researchers use the Vicon Vantage motion-capture system (cameras, PoE+ networking and mounting hardware) to record and analyse movement in the Kinesis Lab. Activities include installing cameras on overhead rails or tripods, routing PoE+ cables to switches and operating the infrared (IR) strobe illumination during captures. Cameras run unattended for extended periods and may be re-positioned between experiments.

Reason for Risk Assessment

To document and control any health, safety and equipment-damage risks introduced by routine operation and maintenance of the Vicon Vantage system in active research.

Overall Current Risk

Low Risk



Average Number of Persons Affected

2  Employees

2  Students

2  Visitors

Current Rating	Hazard Information	Task Status
Low Risk	⚠️ Electricity Cameras and Lock units are powered via IEEE 802.3at PoE+ (= 57 V DC). Damaged RJ-45 leads or improper use of non-compliant switches could expose conductors, causing mild electric shock or short-circuit.	0 0 0
	Measures Currently in place to prevent risk of injury	
	- Only PoE+/PoE switches certified to IEEE 802.3at are used. - Vicon-supplied shielded Cat 5e leads with moulded plugs and ferrites; visual inspection before use. - Switch ports remain de-energised until handshake is complete ("power-on last" rule). - No user access inside camera housings; servicing by Vicon only.	

Potential Rating	Additional Controls Required
Low Risk	No Remedial Actions Entered If there are any reasonably practicable actions which can be taken to reduce the risk associated with this hazard please use the form above to enter them.

Current Rating	Hazard Information	Task Status
Low Risk	⚠️ Hot surfaces Camera heat-sinks and strobe LEDs warm up during prolonged capture; touching fins may cause minor burns. Over-temperature could shorten component life.	0 0 0
	Measures Currently in place to prevent risk of injury	
	- Cameras installed in well-ventilated lab; airflow not obstructed. - Built-in temperature sensors report status to software; over-temp alarm triggers shutdown. - Users avoid direct contact with heat-sink surfaces while powered	

Potential Rating	Additional Controls Required
Low Risk	No Remedial Actions Entered If there are any reasonably practicable actions which can be taken to reduce the risk associated with this hazard please use the form above to enter them.

Current Rating	Hazard Information	Task Status
Low Risk	⚠️ Fall of Object from Height Cameras (~ 1.2 kg) are ceiling- or tripod-mounted; failure of clamps or vibration could drop equipment, injuring personnel or damaging hardware.	0 0 0
	Measures Currently in place to prevent risk of injury	
	- Cameras secured with ¼-20 UNC mounting points and optional Vicon bracket; fasteners torque-checked. - Only stable tripods / certified rails are permitted; regular inspection schedule. - Cables strain-relieved to prevent tugging.	

Potential Rating	Additional Controls Required
Low Risk	No Remedial Actions Entered If there are any reasonably practicable actions which can be taken to reduce the risk associated with this hazard please use the form above to enter them.

Current Rating	Hazard Information	Task Status
Low Risk 	Non Ionising Radiation High-power 850 nm strobe flashes each frame; looking directly into the emitter at close range may cause eye discomfort.	0 0 0
	Measures Currently in place to prevent risk of injury	
	• System software disables strobes when a camera enters preview mode or is uncabled. • Markers and scene layout minimise direct line-of-sight to emitters. • Visitors supervised; safety briefing before demos.	

Potential Rating	Additional Controls Required
Low Risk 	No Remedial Actions Entered If there are any reasonably practicable actions which can be taken to reduce the risk associated with this hazard please use the form above to enter them.