



General Details

Assessor	Samuel Prieto Ayllon
Assessment Date	03/07/2025
Assigned Reviewer	Samuel Prieto Ayllon
Next Review Date	03/07/2026

Signed Off By	Oraib AlKheetanRojas
Signed Off On	19/05/2026
Sign Off Comments	

Operation Assessed	Hyperspectral Camera – Corning microHSI 410 SHARK Operation
--------------------	---

Associated with specific area

-  Basement 2
-  B2 029 (Robotics Lab)
-  CTP

Description of work area and/or activity assessed

Routine laboratory or field operation of the Corning microHSI 410 SHARK hyperspectral camera, including set-up on tripods, mobile robot masts or drone payload rails; connection to host PC or data logger via Gigabit-Ethernet and USB 3.0; external DC power connection; GNSS antenna use; firmware/profile loading; and continuous spectral data capture indoors or outdoors.

Reason for Risk Assessment

To document and control any health, safety, and equipment-damage risks introduced by actively using the microHSI 410 SHARK in research.

Overall Current Risk

Low Risk



Average Number of Persons Affected

2  Employees

2  Students

Current Rating	Hazard Information	Task Status
Low Risk	Electricity The camera is powered by an external +8 V DC ? +16 V DC supply (< 19 W) and communicates via USB 3.0 or Gigabit-Ethernet. Damage to the DC lead or data cables could create a mild electric shock, short-circuit or spark during set-up or relocation. Static-charge (ESD) events may corrupt the CCD/CMOS hybrid detector or FPGA.	0 0 0
	Measures Currently in place to prevent risk of injury	
	• Use only the supplied locking DC connector, observing tip-positive polarity while the power switch is OFF. • “Power-on last, power-off first” rule for both bench and field use. • Visual inspection of insulation and strain relief before each session. • Cables routed clear of walkways and never under tension.	

Potential Rating	Additional Controls Required
Low Risk	No Remedial Actions Entered If there are any reasonably practicable actions which can be taken to reduce the risk associated with this hazard please use the form above to enter them.

Current Rating	Hazard Information	Task Status
Low Risk	Fall of Object from Height The camera (~ 0.73 kg with lens) is often mounted on tripods, robot masts or UAV rails. Loss of clamp integrity or accidental knocks can cause the unit to fall, posing head-injury risk and damaging the optics or diffraction grating.	0 0 0
	Measures Currently in place to prevent risk of injury	
	• Quick-release plates torqued to specification and checked by a second person. • Tripod legs sand-bagged on uneven ground; exclusion zone marked during adjustments. • Visual inspection of mounting rails and screws before each deployment.	

Potential Rating	Additional Controls Required
Low Risk	No Remedial Actions Entered If there are any reasonably practicable actions which can be taken to reduce the risk associated with this hazard please use the form above to enter them.