

Plasticity 1.2.4 Shortcut Key Sheet

3D Viewport

Front view	Num.1
Right view	Num.3
Top view	Num.7
Back view	Ctrl-Num.1
Left view	Ctrl-Num.3
Bottom view	Ctrl-Num.7
Switch perspective / orthographic	Num.5
To center it on the screen	Space
To view it full screen	/ (Slash)
To view it full screen and hide all	. (period)
To toggle overlay display	Alt-Shift-Z
To toggle X-Ray mode	Alt-Z
Control point selection mode	1
Edge selection mode	2
Face selection mode	3
Solid selection mode	4
All selectable mode	Tab
Toggle control point selection mode	Shift-1
Toggle edge selection mode	Shift-2
Toggle face selection mode	Shift-3
Toggle solid selection mode	Shift-4
Select All	A
Select Adjacent	Ctrl-Shift-=
Deselect all	Esc
Invert selection	Alt-A
Select edges included in selection	Ctrl-2
Select faces included in selection	Ctrl-3
Select solids included in selection	Ctrl-4
Hide Selected	Н
Hide Unselected	Shift-H
Hide Unselected Invert Hidden	Shift-H Ctrl-H
Invert Hidden	Ctrl-H
Invert Hidden Unhide All	Ctrl-H Alt-H

Construction plane

From selection (align camera)	Space
From selection (do not align)	Shift-Space
From camera (through orijin)	Ctrl-Space
From camera (select distance)	Ctrl-Shift-Space

Tools

Line	Shift-A
Corner Box	Shift-B
Cylinder	Shift-C

Common Commands

Move	G
Rotate	R
Scale	S
Mirror	Alt-X
Duplicate	Shift-D
Place	Ctrl-D
Explode	Alt-J
Set Material	М
Remove Material	Alt-M

Sketch Commands

Fillet	В
Offset Curve	0
Subdivide Curve	Shift-S
Project	I
Join	J
Trim	Т

Solid Commands

Boolean	Q
Cut	С
Extrude	E
Sweep	Shift-P
Loft	L
Pipe	Р
Fillet	В
Alternative Duplicate	Alt-D
Join	J
Untrim	Alt-T
Offset Face	Shift-O
Delete Face	Shift-Backspace
Offset Curve	0
Imprint	Shift-I
Isoparam	Ctrl-R