
E4 — command jitter on a static hold
mean joint std [mrad]
0
1
2
3
4
5
6
7
SC-on n=0mm
SC-on n=1mm
SC-on n=2mm
SC-on n=4mm
SC-off n=0mm
SC-off n=1mm
SC-off n=2mm
SC-off n=4mm


worst joint, mean-removed
cmd [mrad]
20
10
0
−10
−20
0
1
2
3
4
5
6
time [s]
SC-on n=0mm @ 0.2 Hz
SC-on n=1mm @ 2.0 Hz
SC-on n=2mm @ 2.0 Hz