
Pose jumps are the only source of unbounded commanded velocity
peak commanded joint velocity [rad/s]
10^1
10^0
unbridged (whole jump in one 20 Hz tick)
auto-blended
clip budget 2.5 rad/s
blend cap 1.0 rad/s
blend threshold
(below: left alone)
0.0
0.5
1.0
1.5
2.0
2.5
3.0
pose-jump magnitude Δ [rad, worst joint]