

INDUSMIND AI - INDUSTRIAL TEST MANUAL

Equipment: Pump P-101

Maintenance History:

Pump P-101 failed on 2024-05-12 due to a bearing overheat.

The bearing was replaced.

Routine inspection must be performed every 6 months to comply with safety regulations.

Connections:

Pump P-101 is connected to Valve A-12 and the Main Cooling System.

Safety Compliance:

Operators must wear PPE at all times when servicing Pump P-101.

Warning: High pressure system.