MFE SERVICES SDN. BHD. (952723-P)
No. 2339, Jalan Raja, Mukim Sungai Raya, 84300 Muar, Johor Darul Ta'zim.
Tel : 06-985 6988 / 985 8709 · Fax : 06-985 9806 · Email : mfetsb@gmail.com

Report No.	**MFE/RR/2026/0001**
Job Ref.	**RV-20261019-3**
Issued	**19 OCT 2026**

Layout review pack: primary example: pp. 1–3. Alternative previous-visit layouts: pp. 4–5 (separate hypothetical visits).

FIRE SYSTEM REPAIR REPORT

FIRE FIGHTING & PROTECTION SYSTEM — REPAIR RECORD

CLIENT	Sample Customer Sdn Bhd		
SITE / ADDRESS	Sample Factory - Lot 18, Jalan Contoh 2, 84000 Muar, Johor (invented)		
TELEPHONE / FAX	06-900 0100 / —	CONTACT PERSON	Ms. Nur Aina (sample)
REPAIR DATE	19 OCTOBER 2026	ARRIVAL TIME	09:15
SERVICE CALL NO.	SC-SAMPLE-1019	CONTRACT NO.	MFE/SAMPLE/2026
PREVIOUS VISIT	SV-20261011-94, 11 Oct 2026	APPROVAL	Approved by Lim Wei Ming (sample) · 19 Oct 2026
TECHNICIAN	Ahmad Farid (sample)	REPAIR VISIT NO.	RV-20261019-3

FIRE FIGHTING & PROTECTION SYSTEMS REPAIRED

☑ Automatic Sprinkler System

WE HEREBY CONFIRM THAT THE ATTACHED RECORDS ARE TRUE AND CORRECT AS AT THE TIME OF REPAIR.

REPAIRED BY — MFE SERVICES SDN. BHD.	VERIFIED BY — MFE SERVICES SDN. BHD.	CONFIRMED BY — CUSTOMER
Ahmad Farid (sample) Team: Repair team A (sample) Signature · Date: **19 OCTOBER 2026**	**Lim Wei Ming (sample)** Name, Signature & Company Stamp · Date:	Name, Signature & Company Stamp · Date:

Customer Satisfaction / Comment	☐ Excellent	☐ Satisfactory	☐ Not Satisfactory	Comment:

NOTE :-

1. Repair work on the selected fields is recorded on the following pages. This sample does not certify unlisted fields.
2. Should any abnormal condition occur which might cause further damage to the customer's systems or threaten human safety or the environment, the customer agrees to call MFE immediately for necessary action.
3. Rectification works, parts replacement, piping and wiring works found necessary during this repair visit are quoted and charged separately.
4. MFE is not responsible for any area, room or device that was not made accessible for inspection or testing on the date of service.

OWNER REVIEW MOCK-UP · INVENTED DATA · NOT AN APPROVED REPORT

S

SUMMARY OF REPAIR

Sample Customer Sdn Bhd · Sample Factory

REPAIR VISIT
RV-20261019-3
19 Oct 2026

Rows 1–2 belong to the primary example (previous visit: SV-20261011-94 · 11 Oct 2026). Rows 3–4 index the alternative layouts only; a real repair visit has one previous visit or None.

NO	SYSTEM	LOCATION / UNIT	ITEM	PREVIOUS RESULT	AFTER REPAIR	PAGE
1	**Automatic Sprinkler**	Pump Room	S.A.J Main Water Supply	✗ NOT GOOD	◯ DONE REPAIR	3
2	**Automatic Sprinkler**	Pump Room	Tank Cover	✓ GOOD	◯ DONE REPAIR	3
3	**Fire Alarm** **Alternative: previous repair visit**	Zone 3, Level 2	Smoke Detector	✗ NOT DONE	✗ NOT DONE	4
4	**Hose Reel** **Alternative: no previous visit**	Warehouse, Ground Floor	Hose Reel Nozzle	—	◯ DONE REPAIR	5

AFTER REPAIR

◯ DONE REPAIR	Repair carried out; see the field remark and After photo.
✗ NOT DONE	Repair not carried out; the required remark gives the reason.

BEFORE EVIDENCE

Previous service visit	Previous result, remark and photo.
Previous repair visit	That visit's After result, remark and photo.
No previous visit	Previous Result: —. After photo alone, full width.

READING THIS MOCK-UP

1. All customer, visit, approval and repair details are invented for layout review.
2. Grey boxes stand in for photographs. A missing historic photo is explicitly labelled.
3. The previous visit and its report remain unchanged.

OWNER REVIEW MOCK-UP · INVENTED DATA · NOT AN APPROVED REPORT

1 AUTOMATIC SPRINKLER

Pump Room · Sample Factory

REPAIR VISIT
RV-20261019-3
2 selected fields

Previous visit: SV-20261011-94 · 11 Oct 2026

NO	SECTION / ITEM	PREVIOUS RESULT	AFTER REPAIR	REPAIR REMARK
1	Water Tank / S.A.J Main Water Supply	✗ NOT GOOD	○ DONE REPAIR	Replaced the leaking gate valve; supply restored and checked.
2	Water Tank / Tank Cover	✓ GOOD	○ DONE REPAIR	Replaced the worn cover seal and secured the cover.

PHOTO EVIDENCE — BEFORE / AFTER REPAIR

BEFORE
SV-20261011-94 · 11 Oct 2026
Result: ✗ NOT GOOD

BEFORE PHOTO PLACEHOLDER

Remark: Gate valve leaking at spindle.

AFTER REPAIR
RV-20261019-3 · 19 Oct 2026
Result: ○ DONE REPAIR

AFTER PHOTO PLACEHOLDER

Remark: Replaced the leaking gate valve; supply restored and checked.

1. Water Tank / S.A.J Main Water Supply

BEFORE
SV-20261011-94 · 11 Oct 2026
Result: ✓ GOOD

No photo recorded at previous visit

Remark: — (no remark recorded)

AFTER REPAIR
RV-20261019-3 · 19 Oct 2026
Result: ○ DONE REPAIR

AFTER PHOTO PLACEHOLDER

Remark: Replaced the worn cover seal and secured the cover.

2. Water Tank / Tank Cover

REPAIR DATE	19 Oct 2026	TECHNICIAN	Ahmad Farid (sample)
INITIAL			

OWNER REVIEW MOCK-UP · INVENTED DATA · NOT AN APPROVED REPORT

2	**FIRE ALARM** Zone 3, Level 2 · Sample Factory	REPAIR VISIT **RV-20261019-3** 1 selected field

ALTERNATIVE LAYOUT — PREVIOUS REPAIR VISIT. Separate hypothetical visit; replaces the primary example's previous visit. Cover would show RV-20261015-2 · 15 Oct 2026.

Previous visit: RV-20261015-2 · 15 Oct 2026 · Before uses that repair visit's After evidence.

NO	SECTION / ITEM	PREVIOUS RESULT	AFTER REPAIR	REPAIR REMARK
1	Detector / Smoke Detector	✗ NOT DONE	✗ NOT DONE	Not done: replacement detector is awaiting delivery. Return visit required after the part arrives.

PHOTO EVIDENCE — BEFORE / AFTER REPAIR

BEFORE
RV-20261015-2 · 15 Oct 2026
Result: ✗ NOT DONE

PREVIOUS REPAIR VISIT'S AFTER PHOTO

Remark: Not done: matching replacement detector unavailable.

AFTER REPAIR
RV-20261019-3 · 19 Oct 2026
Result: ✗ NOT DONE

AFTER PHOTO PLACEHOLDER

Remark: Not done: replacement detector is awaiting delivery. Return visit required after the part arrives.

1. Detector / Smoke Detector

REPAIR DATE	19 Oct 2026	TECHNICIAN	Ahmad Farid (sample)
INITIAL			

OWNER REVIEW MOCK-UP · INVENTED DATA · NOT AN APPROVED REPORT

3 HOSE REEL

Warehouse, Ground Floor · Sample Factory

REPAIR VISIT
RV-20261019-3
1 selected field

ALTERNATIVE LAYOUT — NO PREVIOUS VISIT. Separate hypothetical visit. Cover would show Previous visit: None. No Before panel is displayed.

Previous visit: None · No previous visit

NO	SECTION / ITEM	PREVIOUS RESULT	AFTER REPAIR	REPAIR REMARK
1	Hose Reel / Hose Reel Nozzle	—	◯ DONE REPAIR	Replaced the damaged nozzle and checked operation; no leakage observed.

PHOTO EVIDENCE — AFTER REPAIR

AFTER REPAIR
RV-20261019-3 · 19 Oct 2026
Result: ◯ DONE REPAIR

AFTER PHOTO PLACEHOLDER

Remark: Replaced the damaged nozzle and checked operation; no leakage observed.

1. Hose Reel / Hose Reel Nozzle

REPAIR DATE	19 Oct 2026	TECHNICIAN	Ahmad Farid (sample)
INITIAL			

— END OF MOCK-UP —

OWNER REVIEW MOCK-UP · INVENTED DATA · NOT AN APPROVED REPORT