

Fig.3 PANDA2 prediction. These plots are results from a PANDA2 test simulation run (ITYPE=3 in the *.OPT file) of the optimized curved panel after correction of the bug in SUBROUTINE MODE. (See Item no. 804 in the file, ...panda2/doc/panda2/news for a description of how the bug was fixed.) NOTE: the local buckling factor of safety, FSLOC was temporarily increased from 0.1 to 0.999 for the production of this figure.