OPTICAL SENSOR MODULE USER GUIDE

1. Overview

The optical sensor module provides high-speed raster scanning for document capture.

2. Hardware Installation

Mount the sensor assembly securely to the chassis using M3 machine screws.
Connect the 24-pin ribbon cable to connector J1 on the main processing board.

Figure 1: Sensor Assembly and Ribbon Cable Connection Diagram

3. Calibration Procedure

Perform an initial white-balance calibration prior to full-speed raster operations.