


tp-link tl-wr840n

hardware version: v6.20

firmware version: 0.9.1 4.16 v0001.0 Build 180614 Rel.40494n

Network-> MAC Clone



"X TP ClonedMACAddress=" parameter buffer overflow.