DI88S-06

4. No corresponding screen displayed when "Audio" or "Information" switch pressed.



NG

Troubleshoot for each diagnosis.

OK

Check AVC-LAN communication circuit (See page DI-275). 2

NG Repair or replace AVC -LAN circuit.

OK

Replace the multi display.