

✂ Cutting Plan

Job: JOB-2024-001 Material: TEST-MATERIAL-001 Plans: 2

Print Export

8
Total Cuts

91.8%
Efficiency

1220mm
Total Waste

1h 30m
Est. Time

14000mm
Total Stock

Stock Bar #1 - 6000mm

95.0% Efficient 5 cuts 300mm waste

General Instructions:
Deburr all edges after cutting

Cutting Method:
Bandsaw - standard setup

Heat Number:
H12345-2024

Mill Cert:
MC-789456

Cut #	Length (mm)	First Cut Angle	Second Cut Angle	Visual Guide	Qty	Est. Time	Instructions
#1	1200mm	90° Right end	45° Left end		2	24m Angle cuts	Mark with job number after cutting Main beam sections
#2	800mm	45° Right end	90° Left end		1	12m Angle cuts	Drill 10mm hole at 200mm from left end Angled brace
#3	1500mm	90° Right end	90° Left end		1	10m	Standard length piece
#4	1000mm	30° Right end	60° Left end		1	12m Angle cuts	Check angles with protractor before cutting Complex angled cut
OFFCUT	300mm	-	-	Save if ≥300mm	1	-	Tag with: H12345-2024 5.0% waste

Stock Bar #2 - 8000mm

88.5% Efficient 3 cuts 920mm waste

General Instructions:
Use cutting fluid for all cuts

Cutting Method:
Bandsaw - slow feed rate

Heat Number:
H67890-2024

Mill Cert:
MC-123789

Cut #	Length (mm)	First Cut Angle	Second Cut Angle	Visual Guide	Qty	Est. Time	Instructions
#1	2500mm	90° Right end	90° Left end		2	20m	Frame members
#2	1580mm	90° Right end	45° Left end		1	12m Angle cuts	File smooth after cutting angle Corner piece
OFFCUT	920mm	-	-	Save if ≥300mm	1	-	Tag with: H67890-2024 11.5% waste